



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22008913/Eqy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	05/10/2022
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 744J	Veh. Inspected	FBF 7255E
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/054	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	12/09/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA YZF-R15	c.c	150
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	ME138B016B2033687	Colour	BLACK
Odometer	14240 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90-17	PIRELLI	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	110/70-17	PIRELLI	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & O/S BODY.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/08/2022	Inspection Date	12/09/2022
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	