

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008922/UYA3Q2**Date:** 13/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220014670
Claimant Vehicle No :	FBM2069Y	Insured Vehicle No :	SJC7028R
Date of Loss:	07/09/2022	Nature of Claim:	TP
		Claim No:	1016688902SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM2069Y		
Make & Model:	HONDA PCX150, 149cc ABS CVT	Engine No:	KF20E4349009
Reg. Date:	25/08/2017 (Man. Year: 2016)	Chassis No:	MLHKF2083G5349009
Colour:	Blue	Odometer:	6088 km
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90-90-14	Rear Tyre Size:	100-90-14
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,329.00	2,701.70	4,627.30	63.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	300.00	1,360.00	81.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,989.00	3,001.70	5,987.30	66.61
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	8,989.00	2,400.00	6,589.00	73.30
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
Nett Liability (S\$)		2,480.00		

INSPECTION

Date of Assignment:	12/09/2022	
Date Inspected:	12/09/2022	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Serviceable	1,080.00 FL	*- FL
2	1		*FRONT RIM	Serviceable	400.00 FL	*- FL
3	1		*FRONT BRAKE DISC	Not Necessary	225.00 FL	*- FL
4	1		*FRONT RIM BEARING	Not Necessary	80.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	98.00 FL	*- FL
6	1		*WINDSHIELD	Not Necessary	322.00 FL	*- FL
7	1		*HEADLAMP	Scratched	960.00 FL	*800.00 FL
8	1		*LAMP STAY	Not Necessary	320.00 FL	*- FL
9	1		*SIDE MIRROR	Cut	180.00 FL	*115.00 FL
10	1		*HANDLE BAR	Bent	225.00 FL	*225.00 FL
11	1		*SET HANDLE BAR BALANCER	Cut	125.00 FL	*38.00 FL
12	1		*SET HAND GRIP	Not Necessary	70.00 FL	*- FL
13	1		*BRAKE LEVER -R/H	Bent	120.00 FL	*120.00 FL
14	1		*FOOTSTEP PANEL (N/S CUT) (N/S NOT CONSISTENT WITH THE IMPACT)	O/S CUT	380.00 FL	*150.00 FL
15	1		*EXHAUST ASSY	Repair	850.00 FL	*- FL
16	1		*EXHAUST PROTECTOR	Distorted	165.00 FL	*165.00 FL
17	1		*SET FAIRING COVER	Cut / Cracked	1,450.00 FL	*900.00 FL
18	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
19	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
20	2		*FORK OIL SEAL	Not Necessary	56.00 FS	*- FS
21	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
22	1		*REAR BOX	Cut	480.00 FS	*380.00 FS
23	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
24	1		*PCX EMBLEM	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,034.00	2,953.00
- List Item Discount on L Items 10.00/10.00% (\$)	705.00	251.30
Total Parts (\$)	7,329.00	2,701.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO REPAIR BODY FRAME	New	450.00	0.00
3	TO RESPRAY PAINTING	New	650.00	0.00
4	TO PROVIDE LABOUR	New	480.00	300.00
Gross Labour Cost (\$\$)			1,660.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >