

SLE8922T.

TP AYA

Toyota Siesta. 1496cc.

Hui Rong.

NSP1707040107

Front Bumper Defend 485.20 ✓

Front Bumper Clips. m 30(SN) ✓

Front Bumper Side Holder LH. NP 46.20 X

Front Bumper Fog Lamp LH NLM 276.40 X

Front Bumper Fog Lamp Cover LH. Cut 128.50 ✓

Headlamp LH. Overhead 3076.50 ✓

Front LH Fender. Buckled 713.20 ✓

Front LH Fender Inner Shield Defend 216.70 ✓

Front LH Fender Inner Shield Clips. m 30(SN) ✓

Front LH Wheel Rim. NLM 300(SN) X

Front LH Wheel Cap. Cut ~~200(SN)~~ 120(SN)

Front LH Tyre. NP 300(SN) X

SLE 8922T.

Front LH Lower Arm. But 486.30

Front LH Shock Absorber 2 407.40 X

Front LH Knuckle Arm. | $A25.40 \times$
Dmgd

Front LH Wheel Hub c/w Bearing, 350.80 ✓

5467.20

S.N: 180

4100.04

~~800~~ 400

Panel Beatiz

~~80~~ 400

Spring Painting

~~50~~ 30

Wiring.

1060

~~150~~ 30.

To spring full cont.

To remove front undercarriage

~~250~~ 120

to perform wheel alignment.

~~150.80.~~

total: 5' 340.04

4/s: 4.21c.

0 5 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: