



**Section A - Accident Details**

Registration Number	SHF105E
Case Reference Number	TAX/09/22/2023
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN SAY BONG
Type of Accident	Side Swipe
Accident Date and Time	10/9/2022 9:00 AM
Accident Reported Date and Time	10/9/2022 11:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116223
Special Instruction to ARC, if any	TP/ LEFT FRONT PORTION/CHINA TAIPING - LKK
Prepared Date and Time	12/9/2022 10:59 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$8,221.73	\$2,937.08
Total Other Cost	\$580.00	\$100.00
<b>TOTAL COST</b>	<b>\$10,593.73</b>	<b>\$3,837.08 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>GuoQiang (LKK) / AIG</b>
ARC / Surveyor Sign Off Date	<b>12/09/2022 4:38 PM</b>	<b>12/09/2022 4:26 PM</b>
Signature		
Remarks		BEFORE PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quoqiang (LKK) & Email :guoqiang@lkkauto.com HP:82880282

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2210-0023	<b>Invoice Number</b>	
<b>Quotation Date</b>	05.10.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$400.00 ✓
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$400.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
RESPRAY WHEEL CAP	\$180.00	\$0.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,116.00</b>	<b>\$400.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$580.00</b>	<b>\$100.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		48520-80639	ABSORBER SET, SHOCK, FRONT LH	0.00	\$511.40	0.00	\$0.00	Replace	Check
		48069-47060	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$823.20	0.00	\$0.00	Replace	Check
		43212-47040	KNUCKLE, STEERING, LH	0.00	\$717.50	0.00	\$0.00	Replace	Check
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Check
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	Replace
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	Replace
		53852-47041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given
		53828-47070	PROTECTOR, FR FENDER LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given
		53857-12010	RETAINER, FR WHEEL LH	0.00	\$3.50	0.00	\$0.00	Replace	Not Given
		53876-47060	LINER, FR FENDER, LH	1.00	\$227.80	25.00	\$170.85	Replace	Replace
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace
		81185-47890	UNIT, HEADLAMP, LH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	0.00	\$103.70	0.00	\$0.00	Replace	Not Given

X  
X  
X  
X  
X  
✓ SCR  
✓ CUT  
✓ CUT  
X  
X  
X  
X  
✓ TN  
✓ NEC  
✓ BUC  
X  
X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/10/2022

User ID : PohSuan

		52535-50060	RETAINER, FR BUMPER, LH & RH	0.00	\$9.50	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	Replace
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	100.00	\$0.00	Replace	Repair
<b>Total</b>					<b>\$10,306.34</b>		<b>\$2,937.08</b>		

X  
√ NEC  
√ BR  
R

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

2,937.08  
+ 400.00  
+ 500.00  

---

3,837.08

ALL X = NN