

T.K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SJN658K

ESTIMATE

VEHICLE NO : PC8587R
MAKE/MODEL : TOYOTA HIACE
ACC DATE : 30.07.2022

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
LIST PRICE			
1	1 REAR BUMPER	651.90	651.90
2	2 REAR BUMPER SIDE RETAINERS -R/L	89.95	179.90
3	1 REAR TAILLAMP -RH	441.35	441.35
4	1 REAR TAILLAMP LOWER GARNISH	126.20	126.20
5	1 REAR TAILLAMP FILLER PANEL	431.60	431.60
6	2 REAR TAILLAMP SIDE CLIPS	8.50	17.00
			1,847.95
		LESS 25%	461.99
			1,385.96

SPECIAL NETTS ITEM

1	1 (SET) REAR BUMPER CLIP	45.00
		45.00

LABOUR CHARGES :

1	TO CHECK REAR ELECTRICAL WIRING	40.00
2	TO REMOVE AND REPLACE REVERSE SENSORS	60.00
3	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	500.00
4	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	500.00
		1,100.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 2,530.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-1158.20
252
868.65
48
590
1503.65
282
1202