

Huey Yon (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Thursday, 17 November 2022 4:01 PM
To: Huey Yon (LKKAuto)
Subject: Re: CTI-TP SGL 41K-SURVEY BY Taufikh (CS/CTI22008931/Tny3)

Dear Huey Yon,

Audit check done for SGL41K, found rear number plate damaged condition should be dented instead of necessary.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: Thursday, 17 November 2022 3:19 pm
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: CTI-TP SGL 41K-SURVEY BY Taufikh (CS/CTI22008931/Tny3)

Dear Simon,

For your audit.

Best Regards,

Huey Yon | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933