

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLU645L

Make & Model: Honda S2000

Chassis number: AP21100192

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper RH side retainer X	1	\$ 76.00
2	Front bumper LH side retainer X	1	\$ 76.00
3	LH headlamp assy X	1	\$ 2,570.00
4	Front LH fender inner stay X	1	\$ 67.00
5	Front LH fender splash shield X	1	\$ 189.00
6	Front LH fender splash shield extension X	1	\$ 112.00
7	Front LH fender encloser X	1	\$ 89.00
8	Front LH fender signal lamp X	1	\$ 109.00
9	Front LH lower arm X	1	\$ 625.00
10	Front LH lower ar ball joint X	1	\$ 167.00
11	Front LH knuckle arm X	1	\$ 668.00
12	Front LH upper arm X	1	\$ 598.00
13	Front LH wheel bearing X	1	\$ 314.00
14	Front LH wheel bearing hub X	1	\$ 345.00
15	Front LH tie rod end X	1	\$ 152.00
16	Steering rack and pinion X	1	\$ 3,251.00
17	LH side mirror assy X	1	\$ 571.00
18	LH front door X	1	\$ 1,782.00
19	LH front door weatherstrip X	1	\$ 266.00
20	Rear RH lower arm X	1	\$ 632.00
21	Rear RH knuckle arm X	1	\$ 602.00
22	Rear RH upper arm X	1	\$ 421.00
23	Rear RH control arm X	1	\$ 283.00
20	Rear LH lower arm X	1	\$ 632.00
21	Rear LH knuckle arm X	1	\$ 602.00
22	Rear LH upper arm X	1	\$ 421.00
23	Rear LH control arm X	1	\$ 283.00

\$ 15,903.00
 Parts less 20% \$ 3,180.60
 Total \$ 12,722.40

No.	Special Nett Items	Qty	Amount S\$
1	Front bumper (after market) ✓ <i>ML</i>	1	\$ 3,500.00
2	Front bumper centre grille X <i>ML</i>	1	\$ 320.00
3	Front bumper clips ✓ <i>ML</i>	1set	\$ 100.00
4	Front LH wide bodykit fender (after market) ✓ <i>ML</i>	1	\$ 1,850.00
5	Front LH wide bodykit fender joint sealant X <i>ML</i>	1	\$ 120.00
6	Front LH fender splash shield X <i>ML</i>	1	\$ 80.00
7	Brake fluid X	1	\$ 120.00
8	Front LH sport rim ✓ <i>ML</i> (new old take photo)	1	\$ 1,650.00
9	Front LH tyre X	1	\$ 680.00
10	Front LH adjustable shock absorber X	1	\$ 1,550.00
11	RH side rocker panel spoiler (after market) X	1	\$ 1,600.00
12	RH side rocker panel spoiler rivets (after market) X	1set	\$ 150.00
13	RH side rocker panel spoiler clips (after market) X	1set	\$ 100.00
14	Rear RH fender wide bodykit joint sealant ML X	1	\$ 120.00
15	Rear RH fender wide bodykit (after market) X <i>ML</i>	1	\$ 2,230.00
16	Rear RH fender wide bodykit sticker (after market) ✓ <i>ML</i>	1	\$ 185.00
17	Rear LH fender inner side mesh X <i>ML</i>	1	\$ 280.00
18	Rear RH sport rim ✓ <i>ML</i>	1	\$ 1,650.00
19	Rear RH tyre X ✓ <i>ML</i>	1	\$ 680.00
20	Rear RH adjustable shock absorber	1	\$ 1,550.00
21	Rear LH sport rim X	1	\$ 1,650.00
22	Rear LH tyre X <i>ML</i>	1	\$ 680.00
23	Rear LH adjustable shock absorber X	1	\$ 1,550.00
24	Rear bumper (after market) X	1	\$ 2,800.00
25	Rear bumper lower spoiler (after market) ✓ <i>ML</i>	1	\$ 3,280.00
26	LH side rocker panel spoiler (after market) X	1	\$ 1,600.00
27	LH side rocker panel spoiler rivets (after market) X	1set	\$ 150.00
28	LH side rocker panel spoiler clips (after market) X	1set	\$ 100.00
29	LH side rocker panel spoiler sticker X <i>ML</i>	1set	\$ 320.00
30	Rear LH fender wide bodykit joint sealant X	1	\$ 120.00
31	Rear LH fender wide bodykit (after market) X	1	\$ 2,230.00
32	Rear LH fender wide bodykit sticker (after market) X	1	\$ 185.00
33	Rear LH fender inner side mesh X	1	\$ 280.00

Total: \$ 29,640.00

No.	Labour and painting	Amount S\$
-----	---------------------	------------

1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 2,500.00
2	Spray painting on affected areas and panels (Special paint)	\$ 2,200.00
3	Check wiring and lighting system on affected areas	\$ 120.00
4	Apply rust coating chemical on affected areas and panels	\$ 180.00
5	Refocus and adjust headlamps assy	\$ 120.00
6	Test drive and adjust wheel alignment system (before and after)	\$ 200.00
7	Remove and replace front undercarriage parts to assist repair	\$ 580.00
8	Remove and replace front LH door inner mechanism to new door	\$ 200.00
9	Remove and replace rear undercarriage parts to assist repair	\$ 550.00

Total: \$ 6,650.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: 5

Spare Parts: \$ 12,722.40

Special Nett: \$ 29,640.00

Labour: \$ 6,650.00

Total Amount: \$ 49,012.40

After repair photos.

Guo Qiang

8288082

13/9/2022.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display "Under Repair" sign during resurvey
- Parts price to be based on "Prejudice" basis
- Third party insurance claim
- No liability for damage to third party
- Supply of parts to be based on "Prejudice" basis and is not to be used for other purposes

Acknowledged by:

Signature:

Date: