

**ABWIN SERVICE PTE LTD**

17 KAKI BUKIT ROAD 4  
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809  
 Tel: 67139400 Fax: 67139415  
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com  
 Company Reg. No: 201318685G GST Reg. No: 201318685G



**M9 Automobile Pte Ltd**  
**M9 International Pte Ltd**

**ESTIMATED COST: HQQ00668**

**TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**

**ATTN : MOTOR CLAIM DEPARTMENT**

**SJG3798G**  
**TEE CHONG HOCK**

BLOCK 419  
 PASIR RIS DRIVE 6  
 #08-281  
 SINGAPORE,  
 SINGAPORE 510419  
 CONTACT NO : 97773798

DATE : 09-SEP-2022  
 MAKE : TOYOTA  
 MODEL : TOYOTA COROLLA ALTIS 1.6L  
 CVT  
 CHASSIS NO : MR053REH104546350  
 ENGINE NO : 1ZR555281  
 SERVICE ADVISOR : HAZEL  
 PAGE : 1 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

**LIST ITEM**

1	REAR BUMPER	581 676.60	de -
1	REAR BUMPER SIDE RETAINER LH	118.70	de -
1	REAR BUMPER SIDE RETAINER RH	118.70	x nq
1	REAR BUMPER BRACKET LH	65.60	des -
1	REAR BUMPER BRACKET RH	65.60	x }
1	REAR BUMPER REFLECTOR RH	70.00	x } nn
1	REAR BUMPER REFLECTOR LH	70.00	x }
1	REAR BUMPER REINFORCEMENT	395 432.50	? bt -
1	TAIL LAMP RH	410.80	x nn
1	TAIL LAMP LH	275.50 410.80	ana -
1	BOOT LID	754 852.90	bt -
1	BOOT LID HINGE RH	75.60	bt -
1	BOOT LID HINGE LH	75.60	bt -
1	BOOT LID EMBLEM LOGO "TOYOTA"	66.90	wa -
1	BOOT LID EMBLEM "COROLLA"	49.40	wa -
1	BOOT LID EMBLEM "ALTIS"	44.50	de -
1	BOOT LID LOCK	210 432.50	bt -
1	BOOT LID LOCK CATCH	36.60	x nn
1	BOOT LID WEATHERSTRIP	190.10	twi -
1	BOOT LID CENTRE CHROME	220 263.40	ant -
1	REAR END PANEL INNER	670 727.70	bt ✓
1	REAR END PANEL OUTER - photo	727.70	bt -
1	REAR END PANEL TOP GARNISH - photo	202 261.60	de -
1	SPARE TYRE PANEL	946.40	RKp
1	REAR WINDSCREEN	1240 1,686.80	ana -
1	REAR FENDER LH	1050 1,244.80	ana -
1	REAR FENDER INNERSHIELD LH	69.70	x nn

**ABWIN SERVICE PTE LTD**

17 KAKI BUKIT ROAD 4  
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809  
 Tel: 67139400 Fax: 67139415  
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com  
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ABWIN**  
 Service Pte Ltd



M9 Automobile Pte Ltd  
 M9 International Pte Ltd

**ESTIMATED COST: HQQ000668**

**TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**

**ATTN : MOTOR CLAIM DEPARTMENT**

**SJG3798G**

**TEE CHONG HOCK**

BLOCK 419  
 PASIR RIS DRIVE 6  
 #08-281  
 SINGAPORE,  
 SINGAPORE 510419  
 CONTACT NO : 97773798

DATE : 09-SEP-2022  
 MAKE : TOYOTA  
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT  
 CHASSIS NO : MR053REH104546350  
 ENGINE NO : 1ZRX555281  
 SERVICE ADVISOR : HAZEL  
 PAGE : 2 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR FENDER WHEEL HOUSING PANEL INNER LH	423.20 <i>for</i>	
1	REAR FENDER WHEEL HOUSING PANEL OUTER LH	328.80 <i>for</i>	
	<b>Sub Total</b>	<b>10,943.50</b>	<i>6383.90</i> <b>4787.92</b> <b>0.00</b>

**SPECIAL NETT**

10	REAR BUMPER CLIPS	50.00 <i>30ue</i>	
1	BOOT LID SEALANT	50.00 <i>30ue</i>	
1	BOOT LID SENSOR	300.00 <i>X nn</i>	
1	END PANEL SEALANT	50.00 <i>40ue</i>	
1	REAR NUMBER PLATE WITH BRACKET	60.00 <i>45ht</i>	
2	REVERSE SENSOR	720.00 <i>200mm</i>	
1	REVERSE CAMERA	380.00 <i>X nn</i>	
1	SPARE TYRE PANEL SEALANT	50.00 <i>X nn</i>	
1	REAR WINDSCREEN SEALANT	50.00 <i>net</i>	
10	REAR FENDER INNERSHIELD CLIPS	50.00 <i>20X nn</i>	<i>395</i>
	<b>Sub Total</b>	<b>1,760.00</b>	<b>0.00</b>

**LABOUR**

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	2,500.00 <i>1200</i>	
1	TO SPRAY PAINT ON AFFECTED AREAS	2,800.00 <i>1200</i>	
1	TO APPLY UNDERCOATING FOR RUST PROOFING	180.00 <i>60</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	150.00 <i>60</i>	
1	TO DISMANTLE AND REFIX REAR WINDSCREEN COMPONENTS	150.00 <i>120.</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	120.00 <i>40</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	120.00 <i>30</i>	
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	150.00 <i>60</i>	

# ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4  
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809  
 Tel: 67139400 Fax: 67139415  
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com  
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd  
 M9 International Pte Ltd

**ESTIMATED COST: HQQ000668**

**TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**  
**ATTN : MOTOR CLAIM DEPARTMENT**

DATE : 09-SEP-2022  
 MAKE : TOYOTA  
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT  
 CHASSIS NO : MR053REH104546350  
 ENGINE NO : 1ZR555281  
 SERVICE ADVISOR : HAZEL  
 PAGE : 3 OF 3

**SJG3798G**  
**TEE CHONG HOCK**  
 BLOCK 419  
 PASIR RIS DRIVE 6  
 #08-281  
 SINGAPORE,  
 SINGAPORE 510419  
 CONTACT NO : 97773798

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO CHECK WIRING	120.00	40
	<b>Sub Total</b>	<b>6,290.00</b>	<b>2810 0.00</b>

*Taufik 92495741/67563561*  
*12/9/22 @ 240pm*  
*taufik@mantan.com*  
*8 days*  
*umpum, resung after repair*

*4787.92*  
*395*  
*2810*  


---

*7992.92*  
*45\$6400*  
*08 days \**

<b>SUB-TOTAL</b>	<b>18,993.50</b>	<b>0.00</b>
<b>GST - 7 %</b>	<b>1,329.55</b>	<b>0.00</b>
<b>TOTAL</b>	<b>20,323.05</b>	<b>0.00</b>