

ASS. REC BY: T. Guffin

REF: CS/CT 2208955 / Trg3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YP 3746G

Policy No: DMCVSNW00095832204

Claims No: SNM22D206462/C02/KHONGLH

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$53K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSG 3798G Yr Regn: 2016, Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 89669 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053RE #107546350

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front R/Bal. 6 mm

Rear R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/9/2022

D.O.I. 12/9/22

Survey held at Aladin

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/11/22	LS \$6400 confirmed by email (Red 12,593.50, 66%)

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) 11/11/22-typist

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format: Merimen

Lump Sum / T.B.T. / \$6400

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd
 M9 International Pte Ltd

ESTIMATED COST: HQQ000668

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJG3798G
TEE CHONG HOCK
 BLOCK 419
 PASIR RIS DRIVE 6
 #08-281
 SINGAPORE,
 SINGAPORE 510419
 CONTACT NO : 97773798

DATE : 09-SEP-2022
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT
 CHASSIS NO : MR053REH104546350
 ENGINE NO : 1ZRX555281
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	REAR BUMPER	676.60	de /
1	REAR BUMPER SIDE RETAINER LH	118.70	de /
1	REAR BUMPER SIDE RETAINER RH	118.70	x
1	REAR BUMPER BRACKET LH	65.60	dis /
1	REAR BUMPER BRACKET RH	65.60	x
1	REAR BUMPER REFLECTOR RH	70.00	x
1	REAR BUMPER REFLECTOR LH	70.00	?
1	REAR BUMPER REINFORCEMENT	432.50	?
1	TAIL LAMP RH	410.80	x
1	TAIL LAMP LH	410.80	can /
1	BOOT LID	852.90	bt /
1	BOOT LID HINGE RH	75.60	bt /
1	BOOT LID HINGE LH	75.60	bt /
1	BOOT LID EMBLEM LOGO "TOYOTA"	66.90	can /
1	BOOT LID EMBLEM "COROLLA"	49.40	can /
1	BOOT LID EMBLEM "ALTIS"	44.50	can /
1	BOOT LID LOCK	432.50	bt /
1	BOOT LID LOCK CATCH	36.60	x
1	BOOT LID WEATHERSTRIP	190.10	twi /
1	BOOT LID CENTRE CHROME	263.40	cut /
1	REAR END PANEL INNER	727.70	?
1	REAR END PANEL OUTER - photo	727.70	bt /
1	REAR END PANEL TOP GARNISH - photo	261.60	de /
1	SPARE TYRE PANEL	946.40	?
1	REAR WINDSCREEN	1,686.80	two /
1	REAR FENDER LH	1,244.80	buc /
1	REAR FENDER INNERSHIELD LH	69.70	?

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd
 M9 International Pte Ltd

ESTIMATED COST: HQQ000668

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJG3798G
TEE CHONG HOCK
 BLOCK 419
 PASIR RIS DRIVE 6
 #08-281
 SINGAPORE,
 SINGAPORE 510419
 CONTACT NO : 97773798

DATE : 09-SEP-2022
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT
 CHASSIS NO : MR053REH104546350
 ENGINE NO : 1ZRX555281
 SERVICE ADVISOR : HAZEL
 PAGE : 2 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR FENDER WHEEL HOUSING PANEL INNER LH	428.20 <i>for</i>	
1	REAR FENDER WHEEL HOUSING PANEL OUTER LH	328.80 <i>for</i>	
Sub Total		10,943.50	0.00

SPECIAL NETT

10	REAR BUMPER CLIPS	50.00 <i>300</i>	
1	BOOT LID SEALANT	50.00 <i>300</i>	
1	BOOT LID SENSOR	300.00 <i>X</i>	
1	END PANEL SEALANT	50.00 <i>400</i>	
1	REAR NUMBER PLATE WITH BRACKET	60.00 <i>450</i>	
2	REVERSE SENSOR	720.00 <i>200mm</i>	
1	REVERSE CAMERA	380.00 <i>X</i>	
1	SPARE TYRE PANEL SEALANT	50.00 <i>X</i>	
1	REAR WINDSCREEN SEALANT	50.00 <i>net</i>	
10	REAR FENDER INNERSHIELD CLIPS	50.00 <i>20?</i>	
Sub Total		1,760.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	2,500.00 <i>1200</i>	
1	TO SPRAY PAINT ON AFFECTED AREAS	2,800.00 <i>1200</i>	
1	TO APPLY UNDERCOATING FOR RUST PROOFING	180.00 <i>60</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	150.00 <i>60</i>	
1	TO DISMANTLE AND REFIX REAR WINDSCREEN COMPONENTS	150.00 <i>120.</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	120.00 <i>40</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	120.00 <i>30</i>	
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	150.00 <i>60</i>	

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd
 M9 International Pte Ltd

ESTIMATED COST: HQQ000668

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJG3798G
TEE CHONG HOCK
 BLOCK 419
 PASIR RIS DRIVE 6
 #08-281
 SINGAPORE,
 SINGAPORE 510419
 CONTACT NO : 97773798

DATE : 09-SEP-2022
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT
 CHASSIS NO : MR053REH104546350
 ENGINE NO : 1ZR555281
 SERVICE ADVISOR : HAZEL
 PAGE : 3 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO CHECK WIRING	120.00	40
Sub Total		6,290.00	0.00

Taufik 92495741 / 67563521
WP' 12/9/22 @ 240pm
taufik@mantowin
8 days
lumpsum, resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SUB-TOTAL	Signature: 18,993.50	0.00
GST - 7 %	Date: 1,329.55	0.00
TOTAL	20,323.05	0.00

ABWIN SERVICE PTE LTD