

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd
 M9 International Pte Ltd

ESTIMATED COST: HQQ000668

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJG3798G
TEE CHONG HOCK
 BLOCK 419
 PASIR RIS DRIVE 6
 #08-281
 SINGAPORE,
 SINGAPORE 510419
 CONTACT NO : 97773798

DATE : 09-SEP-2022
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT
 CHASSIS NO : MR053REH104546350
 ENGINE NO : 1ZRX555281
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	REAR BUMPER	676.60	de /
1	REAR BUMPER SIDE RETAINER LH	118.70	de /
1	REAR BUMPER SIDE RETAINER RH	118.70	x
1	REAR BUMPER BRACKET LH	65.60	dis /
1	REAR BUMPER BRACKET RH	65.60	x
1	REAR BUMPER REFLECTOR RH	70.00	x
1	REAR BUMPER REFLECTOR LH	70.00	?
1	REAR BUMPER REINFORCEMENT	432.50	?
1	TAIL LAMP RH	410.80	x
1	TAIL LAMP LH	410.80	can /
1	BOOT LID	852.90	bt /
1	BOOT LID HINGE RH	75.60	bt /
1	BOOT LID HINGE LH	75.60	bt /
1	BOOT LID EMBLEM LOGO "TOYOTA"	66.90	can /
1	BOOT LID EMBLEM "COROLLA"	49.40	can /
1	BOOT LID EMBLEM "ALTIS"	44.50	can /
1	BOOT LID LOCK	432.50	bt /
1	BOOT LID LOCK CATCH	36.60	x
1	BOOT LID WEATHERSTRIP	190.10	twi /
1	BOOT LID CENTRE CHROME	263.40	cut /
1	REAR END PANEL INNER	727.70	?
1	REAR END PANEL OUTER - photo	727.70	bt /
1	REAR END PANEL TOP GARNISH - photo	261.60	de /
1	SPARE TYRE PANEL	946.40	?
1	REAR WINDSCREEN	1,686.80	two /
1	REAR FENDER LH	1,244.80	buc /
1	REAR FENDER INNERSHIELD LH	69.70	?

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd
 M9 International Pte Ltd

ESTIMATED COST: HQQ000668

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJG3798G
TEE CHONG HOCK
 BLOCK 419
 PASIR RIS DRIVE 6
 #08-281
 SINGAPORE,
 SINGAPORE 510419
 CONTACT NO : 97773798

DATE : 09-SEP-2022
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT
 CHASSIS NO : MR053REH104546350
 ENGINE NO : 1ZR555281
 SERVICE ADVISOR : HAZEL
 PAGE : 2 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR FENDER WHEEL HOUSING PANEL INNER LH	428.20 <i>for</i>	
1	REAR FENDER WHEEL HOUSING PANEL OUTER LH	328.80 <i>for</i>	
Sub Total		10,943.50	0.00

SPECIAL NETT

10	REAR BUMPER CLIPS	50.00 <i>300</i>	
1	BOOT LID SEALANT	50.00 <i>300</i>	
1	BOOT LID SENSOR	300.00 <i>X</i>	
1	END PANEL SEALANT	50.00 <i>400</i>	
1	REAR NUMBER PLATE WITH BRACKET	60.00 <i>450</i>	
2	REVERSE SENSOR	720.00 <i>200mm</i>	
1	REVERSE CAMERA	380.00 <i>X</i>	
1	SPARE TYRE PANEL SEALANT	50.00 <i>X</i>	
1	REAR WINDSCREEN SEALANT	50.00 <i>net</i>	
10	REAR FENDER INNERSHIELD CLIPS	50.00 <i>20?</i>	
Sub Total		1,760.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	2,500.00 <i>1200</i>	
1	TO SPRAY PAINT ON AFFECTED AREAS	2,800.00 <i>1200</i>	
1	TO APPLY UNDERCOATING FOR RUST PROOFING	180.00 <i>60</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	150.00 <i>60</i>	
1	TO DISMANTLE AND REFIX REAR WINDSCREEN COMPONENTS	150.00 <i>120.</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	120.00 <i>40</i>	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	120.00 <i>30</i>	
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	150.00 <i>60</i>	

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



M9 Automobile Pte Ltd
 M9 International Pte Ltd

ESTIMATED COST: HQQ000668

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SJG3798G
TEE CHONG HOCK
 BLOCK 419
 PASIR RIS DRIVE 6
 #08-281
 SINGAPORE,
 SINGAPORE 510419
 CONTACT NO : 97773798

DATE : 09-SEP-2022
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS 1.6L CVT
 CHASSIS NO : MR053REH104546350
 ENGINE NO : 1ZR555281
 SERVICE ADVISOR : HAZEL
 PAGE : 3 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO CHECK WIRING	120.00	40
Sub Total		6,290.00	0.00

Taufik 92495741 / 67563521
WP' 12/9/22 @ 240pm
taufik@mantowin
8days
lumpsum, resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SUB-TOTAL	Signature: 18,993.50	0.00
GST - 7 %	Date: 1,329.55	0.00
TOTAL	20,323.05	0.00

ABWIN SERVICE PTE LTD