

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Acknowledged by Repairer: SIM301U

Signature: Accident Date : 10/9/2022

Date: Location : YIO CHU KANG ROAD

Model: TOYOTA HARRIER

(30/7/2018)

3P: QX1485A (SPF)

TP SPF Hui Rong

JTEKB36H00J002398

S/No	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>deltd</i>	1,418.45	904	
2	10 pcs	Rear bumper clips <i>new</i>		50.00	
3	2 pcs	Rear bumper screw middle <i>new</i>		20.00	X.
4	1 pc	Rear bumper garnish chrome <i>new</i>		300.00	+
5	1 pc	Rear leg sensor <i>new</i>	780.80	X.	
6	2 pcs	Rear bumper o/s & n/s retainer <i>new</i>	168.00	X	
7	1 pcs	Rear bumper retainer middle <i>new</i>	226.00	+	
8	1 pcs	Rear bumper sponge <i>deltd</i>	176.40		
9	2 pcs	Rear bumper o/s & n/s sponge <i>new</i>	85.60	X.	
10	1 pc	Rear bumper lower diffuser <i>deltd</i>	502.00		
11	1 pc	Rear bumper damper <i>deltd</i>	342.30	X	
12	2 pcs	Rear bumper o/s & n/s reflector <i>new</i>	240.00	+	
13	1 pc	Rear bumper stone guard (Lower) <i>new</i>	696.20	+	
14	8 pcs	Rear bumper stone guard clips <i>new</i>		40.00	X.
15	1 pc	Rear tail gate <i>deltd</i>	2,578.50	1718	
16	1 pc	Rear tail gate weatherstrip <i>new</i>	292.00	X.	
17	1 pc	Rear tail gate Harrier emblem <i>new</i>	93.80		
18	1 pc	Rear tail gate Turbo emblem <i>new</i>	84.30		
19	1 pc	Rear tail gate emblem <i>new</i>	80.00	X.	
20	1 pc	Rear tail gate inner trim <i>new</i>	696.00	+	
21	16 pcs	Rear tail gate inner trim clips <i>new</i>		80.00	+
22	1 pc	Rear tail gate lock (Upper) <i>deltd</i>	392.00	-	
23	1 pc	Rear tail gate lock buzzle <i>new</i>	420.00	+	
24	1 pc	Rear end panel <i>new</i>	1,006.40	+	
25	1 pc	Rear tail gate end inner trim <i>new</i>	498.00	+	
26	6 pcs	Rear tail gate end panel inner trim clips <i>new</i>		30.00	+
27	12 pcs	Rear o/s & n/s fender inner trim clips <i>new</i>		60.00	+
28	2 pcs	Rear o/s & n/s fender inner trim <i>new</i>	1,455.60	X.	
29	1 pc	Rear boot floor tray (Centre) <i>new</i>	596.00	X	
30	2 pcs	Rear boot floor o/s & n/s corner tray <i>new</i>	786.00	+	
31	2 pcs	Rear boot floor o/s & n/s tray (Rear) <i>new</i>	869.00	+	
32	1 pc	Rear n/s air vent garnish <i>new</i>	153.20	X	
33	1 pc	Rear windscreen sealant <i>new</i>		80.00	60
34	1 set	Rear windscreen moulding <i>new</i>	250.00	175	
35	2 pcs	Rear reverse sensor <i>deltd</i>	257.50	580	
Sub Total:			15,644.05	660.00	0.00
			25%	0%	10%
After Less %:			11,733.04	660.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	1,400.00	500	
2		To spray painting.	1,000.00	500	
3		To remove & refit rear windscreen.	180.00	120	
4		To remove & replace rear reverse sensor & camera.	100.00	60	
5		To remove & replace rear tail gate. <i>fitting</i>	100.00	60	
6		To check for fault code and resetting	250.00	X	
7		To check wiring.	80.00	30	
8		To re seal anti rust. <i>1270</i>	100.00	X	
Sub Total:			3,210.00		
Total:			15,603.04		
After Less 20%:			12,482.43		

3279.80

2437.35

S.N: 50.

Admin L
1/5 12/9/22

04 Days.

total: 3757.35

5105.85

Chan San Choon
Director
DipEng, AAE, MIM, MSAE(Aust)



AL 8778 1999
24 hr accident call

Mobil 1
SIM301U ESTIMATE. Pg1



PAYNOW