

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618

Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBT8148B

DOA : 02/09/2022

MAKE/MODEL : HONDA/ CB 150X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- No liability damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 2676

-10%
2407.50

S/No	DESCRIPTION	AMOUNT
1	HANDLER BAR / BT	\$195.00 /
2	UNDER BRACKET / BT	\$298.00 /
3	STEERING CON 1SET / R/C	\$120.00 /
4	BRAKE LEVER / BT	\$45.00 /
5	R/H HANDLER END / CUT	\$48.00 /
6	R/H MIRROR / BR	\$45.00 /
7	VISOR X1 / BR	\$195.00 /
8	VISOR RUBBER BUSH X4 / R/C	\$80.00 /
9	R/H FOOT REST BRACKET / BT	\$165.00 /
10	R/H FRONT FOOT REST / BT	\$85.00 /
11	BRAKE PEDAL / BT	\$90.00 /
12	MUFFLER ASSY / BT	\$780.00 :700 /
13	MUFFLER GUARD / CUT	\$98.00 /
14	MUFFLER JOIN GASKET / R/C	\$25.00 /
15	FAIRING STAY / BT	\$198.00 /
16	RADIATOR ASSY / BT	\$268.00 /
17	COOLANT / R/C	\$50.00 20 /
18		
19	TSP (Towing)	\$80.00 60
20	LABOUR	\$400.00 300

Steno (LKK)
9/9/22, 377

m R
P/P
My R/L
3 1/5

Steno (LKK)
15/9/22

Total :

\$3,265.00 360

P/P = 2767.50