

AGS. REC'DV: TuffinREF: III

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ms Loh Vehicle: IN / OUTVeh No: SHD3560P Yr Regn: 2016 / Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prim C.C. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 710060 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5T DKB3F U 003530448

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: NI / S/Rim / STD A/Rim or _____Tyre Size: F: 195/65R15R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 0 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 8/9/22Survey held at Comfort Wagon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt 2/3

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

TP-III - SUP1474

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Rep. Format: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

TOTAL

Lump Sum / L.B./ (P) _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL

Loke Wei Ylang

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/09/2022
Vehicle Reg. No.:	SHD3560P	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Vehicle Reg. Date:	20/09/2016
Vehicle Colour:	BLUE		
Engine No:	2ZRR923714	Chassis No:	JTDKB3FU003530448
Odometer:	710060 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	4,878.16
Miscellaneous Items	11.00
Labour	1,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,709.16
+ GST 7.00% (S\$)	469.64
Nett Amount (S\$)	7,178.80

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2022)**Parts:** 144 TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3560P/07/09/2022 14:10**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER FOG LAMP	25.00	0.00 <i>cm</i>	*920.00 FL
2	1		*HEADLAMP RH	25.00	0.00 <i>cm</i>	*2,637.60 FL
3	1		*FRONT BUMPER COVER	25.00	0.00 <i>ph</i>	*586.18 FL
4	1		*FRONT BUMPER SIDE BRACKET RH	25.00	0.00 <i>del</i>	*90.75 FL
5	1		*FRONT BUMPER CLIPS	25.00	0.00 <i>del</i>	*22.00 FL
6	1		*FRT FENDER HYBRID EMBLEM RH	25.00	0.00 <i>del</i>	*86.50 FL
7	1		*FRT FENDER SHIELD RH	25.00	0.00 <i>del</i>	*198.50 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	25.00	0.00 <i>del</i>	*77.00 FL
9	1		*FRT WHEEL RIM RH	25.00	0.00 <i>del</i>	*1,570.55 FL
10	1		*WIPER SPARE TANK	25.00	0.00 <i>del</i>	*181.80 FL
11	1		*RENEW FRT ADVERTISEMENT RH	0.00	0.00 <i>del</i>	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

6,470.88

- List Item Discount on L Items (S\$)

1,592.72

Total Parts (S\$)

4,878.16

ComfortDelGro Engineering Pte Ltd/SHD3560P/07/09/2022 14:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	1,100.00
2	SPRAY PAINTING CHARGE	New	500	600.00
3	TUFF KOTE	New	X	60.00
4	CHECK ALL LIGHTING	New	30	60.00
Gross Labour Cost (S\$)				1,820.00

ComfortDelGro Engineering Pte Ltd/SHD3560P/07/09/2022 14:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphi 97495749
'wp' 8/1/22 @ 430 pm
2/3 Resurvey after repair.
Tanphi @ 11/01/2022
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: