

SJ472007. 2016 Nov.

BMW 220i M Sport.

WBA2F32020V688332.

7PALG. Sept 22
Xiao Tony.

Rees Buyer	Dehd	1794	✓
Rees Buyer	Side Holder RH. ^M _n	85.	+
Rees Buyer	Clips. ^X _{lee}	50(SW)	✓
Rees Buyer	Sensor. ^D _{angd}	285.	✓
Tailump	RH. ^C _{uld}	624.	✓
		2703	S.V: 50
		2432.70	
Panel Beatz		400	250
Spry Painting.	580	400	250
Wiring.		50	30
To remove cense sensor.		100	50
To perform diagnostic test.		200	x.

total: 3062.70.

4/s: 2.4K

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Services are subject to confirmation
- Survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Accessory item(s) must be resurveyed and subject to final approval from Insurance Company

2400
3 days

acknowledged by Repairer
e: