

KA...
 To...
 By...
 Date...
 Acknowledged by Repairer
 Signature:
 Date:

SMP 5849 Y. 2019 Oct
 Toyota Noah Hybrid. 1797CC
 ZWR800390297.

7P Chinn.
 Xiao Tong

Rear Number Plate	2115P	30(SN) x
Rear Number Plate Holder	ner	30(SN) x
Rear Bumper Distorted		1025.20 /
Rear Bumper Clips. ner		30(SN) /
Rear Bumper Side Holder x02 Dmg		145.8 x 2 = 291.60 ✓
Rear Bumper Reflector x02 xHP ner		125.6 x 2 = 251.20 ✓
Rear Bumper Tow Cover Delnd		28.10 ✓
Reverse Sensor. Damaged		280(SN) 200(SN)
Rear End Panel Distorted		683.50 /
Rear End Panel Liner		=
Rear End Panel Top Garnish. Delnd		148.60 ✓
Rear End Panel Top Garnish Clips. ner		20(SN) ✓
Rear End Panel Sealant. ner		60(SN) ✓

SMP5849Y

Taillamp x 02	Cracked	$685.1 \times 2 = 1370.20$
Taillamp Lower Apron x 02	Deformed	$178.8 \times 2 = 357.60$
Tailgate	Distorted	1812.70.
Tailgate Weatherstripe	ut	375.10.
Tailgate Lock.	Damaged	420.60.
Tailgate Outer Chrome	Cracked	581.90.
Tailgate Inner Trim Board	Deformed	575.90.
Tailgate Inner Trim Board clips.	in	30(SN)
Tailgate Damper x 02.	HP New	$326.8 \times 2 = 653.60.$
Tailgate Glass Moulding	HP	185.90.
Tailgate Glass Sealant	New	60(SN)
Toyota Logo.	New	78.40.
Hybrid Emblem.	New	58.20.

SMP 5849Y.

Rear Fender Lower Trim Board ^{Deformed} x02 781x2 = 1562 ✓
Rear Fender Lower Trim Board clips. ^{was} 60(SN) ✓
Floor Panel. ^{Rep's} 925-80. ✓
^{torn} 845-10 ✓
Floor Panel Top Board ^{Deformed} 128-70. ✓
Rear Jack Cover. 1052930 SN: 460
7876-97

Panel Beating
Spray Painting.
Wiring.
To remove reverse sensor 2550
To remove rear camera.
To remove upholstery.
To remove tailgate g/s
To transfer tailgate fittings.
To spray buff coat.

1400	1100
1400	1000
100	30
100	50
100	50
150	80
180	120
150	60
150	60

total 10906.97
4/5: 8-7K
06 Days.

8-7K
6 days