



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Ref: CS/GAI22008951/Kvy3e2 Date: 09/01/2023 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCA 83U	Veh. Inspected	JRF 8379	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVP000001244	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	12/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	ACR507105145	Colour	METALLIC WHITE	
Odometer	225082 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	ROADSTER	7 mm	
L/H Front Tyre	215/55 R17	ROADSTER	7 mm	
R/H Rear Tyre	215/55 R17	ROADSTER	7 mm	
L/H Rear Tyre	215/55 R17	ROADSTER	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/09/2022	Inspection Date	20/09/2022	
Survey held at	RS AUTO SERVICES 160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	