

MS Car Auto Pte Ltd

Tel: 6385-1838 / 9725 4442 Fax: 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com / msgroupoffice@gmail.com

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

SJE : nercus

Vehicle Nos : SKN 5622T

Date of Survey : 13/09/22

Model : HONDA VEZEL

Contacts : 9009 6608

Year :

** AGREED COR and Days with SJE **

the ght. After leg.

Amount :

Nos.	PARTS	QTY	UNIT S\$	Total S\$	REMARKS IF ANY
REAR PORTION ONLY					
1	TAILGATE <i>body</i>	1	\$ 953.30	\$ 953.30	—
2	TAILGATE MOULDING <i>one</i>	1	\$ 123.80	\$ 123.80	—
3	TAILGATE GARNISH <i>one</i>	1	\$ 395.20	\$ 395.20	— 248
4	TAILGATE LOGO <i>one</i>	1	\$ 32.90	\$ 32.90	—
5	TAILGATE VEZEL WORDING <i>one</i>	1	\$ 38.60	\$ 38.60	—
6	TAILGATE REFLECTOR LH <i>one</i>	1	\$ 413.90	\$ 413.90	— 320
7	TAILGATE REFLECTOR RH <i>one</i>	1	\$ 413.90	\$ 413.90	— 320
8	TAILGATE HANDLE SWITCH <i>one</i>	1	\$ 131.70	\$ 131.70	X
9	TAILGATE NO. PLATE LAMP LH <i>one</i>	1	\$ 49.90	\$ 49.90	X
10	TAILGATE NO. PLATE LAMP RH <i>one</i>	1	\$ 49.90	\$ 49.90	X
11	TAILGATE HINGE LH <i>one</i>	1	\$ 50.90	\$ 50.90	X
12	TAILGATE HINGE RH <i>one</i>	1	\$ 50.90	\$ 50.90	X
13	TAILGATE ABSORBER LH <i>one</i>	1	\$ 192.50	\$ 192.50	X
14	TAILGATE ABSORBER RH <i>one</i>	1	\$ 192.50	\$ 192.50	X
15	TAILGATE INNER BOARD <i>Del/10.1</i>	1	\$ 270.30	\$ 270.30	—
16	TAILGATE LOCK <i>body</i>	1	\$ 356.20	\$ 356.20	— 180.20
17	TAILGATE WEATHERSTRIP <i>body</i>	1	\$ 198.90	\$ 198.90	— 162.30
18	TAILGATE STOPPER <i>one</i>	2	\$ 29.40	\$ 58.80	X
19	TAIL LAMP LH <i>one</i>	1	\$ 552.80	\$ 552.80	— 482
20	TAIL LAMP RH <i>one</i>	1	\$ 552.80	\$ 552.80	— 482
21	TAIL LAMP PANEL LH <i>one</i>	1	\$ 178.20	\$ 178.20	X
22	TAIL LAMP PANEL RH <i>one</i>	1	\$ 178.20	\$ 178.20	X
23	REAR BUMPER <i>body</i>	1	\$ 762.70	\$ 762.70	—
24	REAR BUMPER RETAINER LH <i>body</i>	1	\$ 16.40	\$ 16.40	—
25	REAR BUMPER RETAINER RH <i>body</i>	1	\$ 16.40	\$ 16.40	—
26	REAR BUMPER LH <i>side</i>	1	\$ 195.80	\$ 195.80	—
27	REAR BUMPER RH <i>side</i>	1	\$ 195.80	\$ 195.80	—
28	REAR END PANEL <i>body</i>	1	\$ 580.30	\$ 580.30	— 517
29	REAR END PANEL TOP GARNISH <i>one</i>	1	\$ 102.50	\$ 102.50	—
30	REAR END PANEL SENSOR <i>one</i>	1	\$ 121.50	\$ 121.50	— 80
31	REAR END PANEL SENSOR BUZZER <i>one</i>	1	\$ 98.70	\$ 98.70	— 60.80
32	REAR WELL PANEL <i>one</i>	1	\$ 858.80	\$ 858.80	X
33	REAR WELL PANEL TOP BOARD <i>one</i>	1	\$ 470.20	\$ 470.20	— 245.60
34	REAR WELL PANEL TOOL TRAY <i>one</i>	1	\$ 173.30	\$ 173.30	X
35	REAR WELL PANEL BATTERY <i>one</i>	1	\$ 2,509.90	\$ 2,509.90	X
36	REAR WELL PANEL LOWER COVER <i>one</i>	1	\$ 213.20	\$ 213.20	—
37	REAR WELL PANEL TOW BRACKET <i>one</i>	1	\$ 105.90	\$ 105.90	X
38	REAR CHASSIS FRAME LH <i>one</i>	1	\$ 567.80	\$ 567.80	X
39	REAR CHASSIS FRAME RH <i>one</i>	1	\$ 567.80	\$ 567.80	X
40	REAR CHASSIS TOP PANEL LH <i>one</i>	1	\$ 225.30	\$ 225.30	X
41	REAR CHASSIS TOP PANEL RH <i>one</i>	1	\$ 225.30	\$ 225.30	X
42	REAR FENDER GARNISH LH <i>one</i>	1	\$ 222.80	\$ 222.80	X
43	REAR FENDER GARNISH RH <i>one</i>	1	\$ 222.80	\$ 222.80	X
44	REAR FENDER INNER BOARD LH <i>Del/10.1</i>	1	\$ 589.70	\$ 589.70	— 366
45	REAR FENDER INNER BOARD RH <i>Del/10.1</i>	1	\$ 589.70	\$ 589.70	— 366
46	REAR FENDER AIR VENT LH <i>one</i>	1	\$ 33.10	\$ 33.10	X
47	REAR FENDER AIR VENT RH <i>one</i>	1	\$ 33.10	\$ 33.10	X
48	REAR FENDER SHIELD LH <i>one</i>	1	\$ 182.10	\$ 182.10	X
49	REAR FENDER SHIELD RH <i>one</i>	1	\$ 182.10	\$ 182.10	X
50	EXHAUST SILENCER BOX <i>one</i>	1	\$ 741.70	\$ 741.70	X
51	EXHAUST ALUMINIUM BOARD <i>one</i>	1	\$ 135.70	\$ 135.70	X

6751.8

52	EXHAUST CENTER PIPE	1	\$ 593.50	\$ 593.50	X
		Total Price		\$ 16,970.00	
		Less 20%		\$ 3,394.00	
		Sub Total Price		\$ 13,576.00	

Nos.	PARTS	QTY	UNIT S\$	Total S\$	REMARKS IF ANY
	REAR PORTION ONLY				
1	REAR NO. PLATE SET	1	\$ 65.00	\$ 65.00	X
2	WINDSCREEN SEALANT	1	\$ 100.00	\$ 100.00	40
3	TAILGATE GARNISH CLIPS SET	1	\$ 40.00	\$ 40.00	X
4	TAILGATE INNER BOARD CLIPS SET	1	\$ 60.00	\$ 60.00	50
5	TAIL LAMP CLIPS	2	\$ 50.00	\$ 100.00	X
6	TAIL LAMP PANEL SEALANT	2	\$ 60.00	\$ 120.00	X
7	REAR BUMPER REVERSE SENSOR	2	\$ 280.00	\$ 560.00	200
8	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00	50
9	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00	50
10	REAR END PANEL TOP GARNISH CLIPS SET	1	\$ 50.00	\$ 50.00	X
11	REAR WELL PANEL SEALANT	1	\$ 120.00	\$ 120.00	X
12	REAR FENDER INNER BOARD CLIPS SET	2	\$ 60.00	\$ 120.00	X
	Total			\$ 1,515.00	390

Nos.	Claims Details : Labour and Spray Painting	Total S\$	REMARKS IF ANY
	REAR PORTION ONLY		
1	Labour to panel beat/cut/weld affected panels, realign and refit/replace necessary affected parts	\$ 2,200.00	1000
2	To putty and spray paint on accident affected portion	\$ 1,800.00	900
3	To remove and transfer rear windscreen to new tailgate	\$ 180.00	120
4	To transfer components to new tailgate	\$ 120.00	60
5	To disconnect/reconnect and check for proper wiring and electrical function	\$ 100.00	20
6	To apply anti rust coating	\$ 120.00	60
7	To remove and reinstall rear compartment trims	\$ 100.00	60
8	To remove and replace exhaust system	\$ 250.00	60
9	To diagnostic reset fault code back to manufactory setting	\$ 450.00	11
10	To dismantle and reinstall petrol tank for replace rear well panel	\$ 350.00	11
11	To dismantle and replace rear bumper reverse sensor with distance test	\$ 100.00	11
12	To dismantle and reinstall rear passenger seat for replace rear well panel	\$ 280.00	11
13	To check water leakage test of accident portion	\$ 80.00	11
	Total	\$ 6,130.00	2280

Nos.	PARTS	QTY	UNIT S\$	Total S\$	REMARKS IF ANY
	FRONT PORTION ONLY				
53	BONNET	1	\$ 892.20	\$ 892.20	X
54	BONNET HINGE LH	1	\$ 116.50	\$ 116.50	X
55	BONNET HINGE RH	1	\$ 116.50	\$ 116.50	X
56	BONNET STOPPER	4	\$ 54.00	\$ 216.00	X
57	BONNET LOCK	1	\$ 259.50	\$ 259.50	X
58	HEADLAMP LH	1	\$ 1,923.50	\$ 1,923.50	—
59	HEADLAMP RH	1	\$ 1,923.50	\$ 1,923.50	—
60	HEADLAMP CHROME LH	1	\$ 78.90	\$ 78.90	X
61	HEADLAMP CHROME RH	1	\$ 78.90	\$ 78.90	X
62	HEADLAMP GARNISH LH	1	\$ 113.49	\$ 113.49	X
63	HEADLAMP GARNISH RH	1	\$ 143.49	\$ 143.49	X
64	HEADLAMP BRACKET LH	1	\$ 125.40	\$ 125.40	—
65	HEADLAMP BRACKET RH	1	\$ 125.40	\$ 125.40	—
66	GRILLE	1	\$ 560.80	\$ 560.80	—

84.50
84.50
318.20

67	GRILLE LOGO	512	1	\$ 28.20	\$ 28.20	/
68	GRILLE CHROME	CN	1	\$ 342.60	\$ 342.60	/ 280
69	GRILLE BRACKET TOP	17	1	\$ 239.50	\$ 239.50	X
70	GRILLE BRACKET CENTER	17	1	\$ 118.70	\$ 118.70	X
71	GRILLE BRACKET LH	17	1	\$ 69.50	\$ 69.50	X
72	GRILLE BRACKET RH	17	1	\$ 69.50	\$ 69.50	X
73	FRONT BUMPER	DE	1	\$ 817.90	\$ 817.90	/ 762.20
74	FRONT BUMPER FOG LAMP LH	CN 701	1	\$ 308.20	\$ 308.20	/
75	FRONT BUMPER FOG LAMP RH	CN 701	1	\$ 308.20	\$ 308.20	/
76	FRONT BUMPER FOG LAMP COVER LH	701	1	\$ 113.70	\$ 113.70	/
77	FRONT BUMPER FOG LAMP COVER RH	701	1	\$ 113.70	\$ 113.70	/
78	FRONT BUMPER TOW COVER	17	1	\$ 77.20	\$ 77.20	X
79	FRONT BUMPER LOWER LIP	17	1	\$ 458.30	\$ 458.30	X
80	FRONT BUMPER LOWER RUBBER	17	1	\$ 84.90	\$ 84.90	X
81	FRONT BUMPER GRILLE	CN	1	\$ 166.80	\$ 166.80	/ 102
82	FRONT BUMPER SIDE RETAINER LH	504	1	\$ 89.60	\$ 89.60	/ 60
83	FRONT BUMPER SIDE RETAINER RH	504	1	\$ 89.60	\$ 89.60	/ 60
84	FRONT BUMPER REINFORCEMENT	105	1	\$ 321.70	\$ 321.70	/
85	FRONT BUMPER REINFORCEMENT COVER LH	105	1	\$ 76.60	\$ 76.60	X
86	FRONT BUMPER REINFORCEMENT COVER RH	105	1	\$ 76.60	\$ 76.60	X
87	FRONT FENDER LH	17	1	\$ 498.90	\$ 498.90	X
88	FRONT FENDER RH	17	1	\$ 498.90	\$ 498.90	X
89	FRONT FENDER GARNISH LH	17	1	\$ 189.90	\$ 189.90	X
90	FRONT FENDER GARNISH RH	17	1	\$ 189.90	\$ 189.90	X
91	FRONT FENDER SHIELD LH	17	1	\$ 198.20	\$ 198.20	X
Nos.	PARTS		QTY	UNIT \$	Total \$	
FRONT PORTION ONLY						
92	FRONT FENDER SHIELD RH	17	1	\$ 198.20	\$ 198.20	X
93	FRONT FENDER BRACKET LH	17	1	\$ 98.50	\$ 98.50	X
94	FRONT FENDER BRACKET RH	17	1	\$ 98.50	\$ 98.50	X
95	SUPPORT PANEL	504	1	\$ 576.20	\$ 576.20	/
96	SUPPORT PANEL TOP COVER	DE/701	1	\$ 286.20	\$ 286.20	/
97	AIR DUCT	701	1	\$ 97.50	\$ 97.50	/
98	AIR DUCT HOSE	17	1	\$ 35.40	\$ 35.40	X
99	HORN LH	17	1	\$ 98.70	\$ 98.70	X
100	HORN RH	17	1	\$ 98.70	\$ 98.70	X
101	AIRCON CONDENSOR	504/pas	1	\$ 950.20	\$ 950.20	/ 810
102	AIRCON CONDENSOR GUIDE LH	17	1	\$ 98.60	\$ 98.60	X
103	AIRCON CONDENSOR GUIDE RH	17	1	\$ 98.60	\$ 98.60	X
104	AIRCON TEMPERATURE SENSOR	17	1	\$ 118.60	\$ 118.60	/
105	RADIATOR	504/pas	1	\$ 1,250.70	\$ 1,250.70	/
Total Price					\$ 16,325.48	
Less 20%					\$ 3,265.10	
Sub Total Price					\$ 13,060.38	9812.7

Nos.	PARTS	QTY	UNIT \$	Total \$	REMARKS IF ANY
	FRONT PORTION ONLY				
13	FRONT NO. PLATE SET	1	\$ 65.00	\$ 65.00	40
14	BONNET INNER MAT CLIPS SET	1	\$ 60.00	\$ 60.00	x
15	GRILLE CLIPS SET	1	\$ 50.00	\$ 50.00	x
16	FRONT BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00	50
17	FRONT FENDER SHIELD CLIPS SET	2	\$ 60.00	\$ 120.00	x
18	SUPPORT PANEL SEALANT	1	\$ 80.00	\$ 80.00	x
19	SUPPORT PANEL COVER CLIPS SET	1	\$ 50.00	\$ 50.00	x
20	AIR DUCT CLIPS SET	1	\$ 20.00	\$ 20.00	0
21	AIRCON GAS	1	\$ 60.00	\$ 60.00	30
22	RADIATOR COOLANT	1	\$ 120.00	\$ 120.00	20
		Total		\$ 705.00	

Nos.	Claims Details : Labour and Spray Painting	Total \$	REMARKS IF ANY
FRONT PORTION ONLY			
14	Labour to panel beat/cut/weld affected panels, realign and refit/ replace necessary affected parts	\$ 1,600.00	800
15	To putty and spray paint on accident affected portion	\$ 1,400.00	800

16	To disconnect/reconnect and check for proper wiring and electrical function			\$ 100.00	20
17	To apply anti rust coating			\$ 120.00	40
18	To dismantle and reinstall radiator with high pressure test			\$ 120.00	
19	To dismantle and reinstall aircon condensor with top up gas			\$ 120.00	3100
		Total		\$ 3,460.00	

1760

PARTS TOTAL \$ 28,856.38
 LABOUR TOTAL \$ 9,590.00
OVERALL TOTAL \$ 38,446.38

NAME OF SURVEYOR :

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P 16564.5
 202
 P-13251.6
 S.N. 520
 1-4040
 17811.6
 202
 14249