

ASS. REC. BY: Marcus

REF:

CS/GRB22008952/Uny3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SKN56227

Yr Regn:

29/06/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 4/11/22

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 14200

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Preli. Report

Final Report

Ref 13k

4/11/22 4/5 @ 14.200 in brief Desmond
(Ref, 24246.38, 6390)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	457E
Vehicle Details	
Vehicle No.:	SKN5427T
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2022
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	L15B5554326
Chassis No.:	RU11304317
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,148.00
Original Registration Date:	29 Jun 2018
First Registration Date:	29 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$11,608.00 <i>sfuy</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2028
PARF Rebate Amount:	\$8,706.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,426.00
COE Rebate Amount:	\$21,096.00
Total Rebate Amount:	\$29,802.00

The information contained herein is correct as at 13 Sep 2022

OK

MS Car Auto Pte Ltd

Tel: 6385-1838 / 9725 4442 Fax: 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com / msgruoffice@gmail.com

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

SJE : nercus

Vehicle Nos : SKN 5622T

Date of Survey : 13/09/22

Model : HONDA VEZEL

Contacts : 9009 6608

Year :

** AGREED COR and Days with SJE **

the ph. After rep.

Amount :

Nos.	PARTS	QTY	UNIT \$	Total \$	REMARKS IF ANY
REAR PORTION ONLY					
1	TAILGATE <i>30g.20</i>	1	\$ 953.30	\$ 953.30	—
2	TAILGATE MOULDING <i>one</i>	1	\$ 123.80	\$ 123.80	—
3	TAILGATE GARNISH <i>one</i>	1	\$ 395.20	\$ 395.20	— 248
4	TAILGATE LOGO <i>one</i>	1	\$ 32.90	\$ 32.90	—
5	TAILGATE VEZEL WORDING <i>one</i>	1	\$ 38.60	\$ 38.60	—
6	TAILGATE REFLECTOR LH <i>one</i>	1	\$ 413.90	\$ 413.90	— 320
7	TAILGATE REFLECTOR RH <i>one</i>	1	\$ 413.90	\$ 413.90	— 320
8	TAILGATE HANDLE SWITCH <i>one</i>	1	\$ 131.70	\$ 131.70	—
9	TAILGATE NO. PLATE LAMP LH <i>one</i>	1	\$ 49.90	\$ 49.90	—
10	TAILGATE NO. PLATE LAMP RH <i>one</i>	1	\$ 49.90	\$ 49.90	—
11	TAILGATE HINGE LH <i>one</i>	1	\$ 50.90	\$ 50.90	—
12	TAILGATE HINGE RH <i>one</i>	1	\$ 50.90	\$ 50.90	—
13	TAILGATE ABSORBER LH <i>one</i>	1	\$ 192.50	\$ 192.50	—
14	TAILGATE ABSORBER RH <i>one</i>	1	\$ 192.50	\$ 192.50	—
15	TAILGATE INNER BOARD <i>one</i>	1	\$ 270.30	\$ 270.30	—
16	TAILGATE LOCK <i>one</i>	1	\$ 356.20	\$ 356.20	—
17	TAILGATE WEATHERSTRIP <i>one</i>	1	\$ 198.90	\$ 198.90	—
18	TAILGATE STOPPER <i>one</i>	2	\$ 29.40	\$ 58.80	—
19	TAIL LAMP LH <i>one</i>	1	\$ 552.80	\$ 552.80	—
20	TAIL LAMP RH <i>one</i>	1	\$ 552.80	\$ 552.80	—
21	TAIL LAMP PANEL LH <i>one</i>	1	\$ 178.20	\$ 178.20	—
22	TAIL LAMP PANEL RH <i>one</i>	1	\$ 178.20	\$ 178.20	—
23	REAR BUMPER <i>one</i>	1	\$ 762.70	\$ 762.70	—
24	REAR BUMPER RETAINER LH <i>one</i>	1	\$ 16.40	\$ 16.40	—
25	REAR BUMPER RETAINER RH <i>one</i>	1	\$ 16.40	\$ 16.40	—
26	REAR BUMPER LH <i>side</i>	1	\$ 195.80	\$ 195.80	—
27	REAR BUMPER RH <i>side</i>	1	\$ 195.80	\$ 195.80	—
28	REAR END PANEL <i>one</i>	1	\$ 580.30	\$ 580.30	—
29	REAR END PANEL TOP GARNISH <i>one</i>	1	\$ 102.50	\$ 102.50	—
30	REAR END PANEL SENSOR <i>one</i>	1	\$ 121.50	\$ 121.50	—
31	REAR END PANEL SENSOR BUZZER <i>one</i>	1	\$ 98.70	\$ 98.70	—
32	REAR WELL PANEL <i>one</i>	1	\$ 858.80	\$ 858.80	—
33	REAR WELL PANEL TOP BOARD <i>one</i>	1	\$ 470.20	\$ 470.20	—
34	REAR WELL PANEL TOOL TRAY <i>one</i>	1	\$ 173.30	\$ 173.30	—
35	REAR WELL PANEL BATTERY <i>one</i>	1	\$ 2,509.90	\$ 2,509.90	—
36	REAR WELL PANEL LOWER COVER <i>one</i>	1	\$ 213.20	\$ 213.20	—
37	REAR WELL PANEL TOW BRACKET <i>one</i>	1	\$ 105.90	\$ 105.90	—
38	REAR CHASSIS FRAME LH <i>one</i>	1	\$ 567.80	\$ 567.80	—
39	REAR CHASSIS FRAME RH <i>one</i>	1	\$ 567.80	\$ 567.80	—
40	REAR CHASSIS TOP PANEL LH <i>one</i>	1	\$ 225.30	\$ 225.30	—
41	REAR CHASSIS TOP PANEL RH <i>one</i>	1	\$ 225.30	\$ 225.30	—
42	REAR FENDER GARNISH LH <i>one</i>	1	\$ 222.80	\$ 222.80	—
43	REAR FENDER GARNISH RH <i>one</i>	1	\$ 222.80	\$ 222.80	—
44	REAR FENDER INNER BOARD LH <i>one</i>	1	\$ 589.70	\$ 589.70	—
45	REAR FENDER INNER BOARD RH <i>one</i>	1	\$ 589.70	\$ 589.70	—
46	REAR FENDER AIR VENT LH <i>one</i>	1	\$ 33.10	\$ 33.10	—
47	REAR FENDER AIR VENT RH <i>one</i>	1	\$ 33.10	\$ 33.10	—
48	REAR FENDER SHIELD LH <i>one</i>	1	\$ 182.10	\$ 182.10	—
49	REAR FENDER SHIELD RH <i>one</i>	1	\$ 182.10	\$ 182.10	—
50	EXHAUST SILENCER BOX <i>one</i>	1	\$ 741.70	\$ 741.70	—
51	EXHAUST ALUMINIUM BOARD <i>one</i>	1	\$ 135.70	\$ 135.70	—

6751.8

52	EXHAUST CENTER PIPE	1	\$ 593.50	\$ 593.50
		Total Price		\$ 16,970.00
		Less 20%		\$ 3,394.00
		Sub Total Price		\$ 13,576.00

X

Nos.	PARTS	QTY	UNIT \$	Total \$	REMARKS IF ANY
	REAR PORTION ONLY				
1	REAR NO. PLATE SET	1	\$ 65.00	\$ 65.00	X
2	WINDSCREEN SEALANT	1	\$ 100.00	\$ 100.00	40
3	TAILGATE GARNISH CLIPS SET	1	\$ 40.00	\$ 40.00	X
4	TAILGATE INNER BOARD CLIPS SET	1	\$ 60.00	\$ 60.00	50
5	TAIL LAMP CLIPS	2	\$ 50.00	\$ 100.00	X
6	TAIL LAMP PANEL SEALANT	2	\$ 60.00	\$ 120.00	X
7	REAR BUMPER REVERSE SENSOR	2	\$ 280.00	\$ 560.00	200
8	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00	50
9	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00	50
10	REAR END PANEL TOP GARNISH CLIPS SET	1	\$ 50.00	\$ 50.00	X
11	REAR WELL PANEL SEALANT	1	\$ 120.00	\$ 120.00	X
12	REAR FENDER INNER BOARD CLIPS SET	2	\$ 60.00	\$ 120.00	X
	Total			\$ 1,515.00	390

Nos.	Claims Details : Labour and Spray Painting	Total \$	REMARKS IF ANY
	REAR PORTION ONLY		
1	Labour to panel beat/cut/weld affected panels, realign and refit/replace necessary affected parts	\$ 2,200.00	1000
2	To putty and spray paint on accident affected portion	\$ 1,800.00	900
3	To remove and transfer rear windscreen to new tailgate	\$ 180.00	120
4	To transfer components to new tailgate	\$ 120.00	60
5	To disconnect/reconnect and check for proper wiring and electrical function	\$ 100.00	20
6	To apply anti rust coating	\$ 120.00	60
7	To remove and reinstall rear compartment trims	\$ 100.00	60
8	To remove and replace exhaust system	\$ 250.00	60
9	To diagnostic reset fault code back to manufactory setting	\$ 450.00	X
10	To dismantle and reinstall petrol tank for replace rear well panel	\$ 350.00	X
11	To dismantle and replace rear bumper reverse sensor with distance test	\$ 100.00	X
12	To dismantle and reinstall rear passenger seat for replace rear well panel	\$ 280.00	X
13	To check water leakage test of accident portion	\$ 80.00	X
	Total	\$ 6,130.00	2280

Nos.	PARTS	QTY	UNIT \$	Total \$	REMARKS IF ANY
	FRONT PORTION ONLY				
53	BONNET	1	\$ 892.20	\$ 892.20	X
54	BONNET HINGE LH	1	\$ 116.50	\$ 116.50	X
55	BONNET HINGE RH	1	\$ 116.50	\$ 116.50	X
56	BONNET STOPPER	4	\$ 54.00	\$ 216.00	X
57	BONNET LOCK	1	\$ 259.50	\$ 259.50	X
58	HEADLAMP LH	1	\$ 1,923.50	\$ 1,923.50	—
59	HEADLAMP RH	1	\$ 1,923.50	\$ 1,923.50	—
60	HEADLAMP CHROME LH	1	\$ 78.90	\$ 78.90	X
61	HEADLAMP CHROME RH	1	\$ 78.90	\$ 78.90	X
62	HEADLAMP GARNISH LH	1	\$ 113.49	\$ 113.49	X
63	HEADLAMP GARNISH RH	1	\$ 143.49	\$ 143.49	X
64	HEADLAMP BRACKET LH	1	\$ 125.40	\$ 125.40	84.50
65	HEADLAMP BRACKET RH	1	\$ 125.40	\$ 125.40	84.50
66	GRILLE	1	\$ 560.80	\$ 560.80	318.20

67	GRILLE LOGO	SLB	1	\$ 28.20	\$ 28.20	/
68	GRILLE CHROME	CN	1	\$ 342.60	\$ 342.60	X 280
69	GRILLE BRACKET TOP	17	1	\$ 239.50	\$ 239.50	X
70	GRILLE BRACKET CENTER	17	1	\$ 118.70	\$ 118.70	X
71	GRILLE BRACKET LH	17	1	\$ 69.50	\$ 69.50	X
72	GRILLE BRACKET RH	17	1	\$ 69.50	\$ 69.50	X
73	FRONT BUMPER	DE	1	\$ 817.90	\$ 817.90	X 762.20
74	FRONT BUMPER FOG LAMP LH	CN 701	1	\$ 308.20	\$ 308.20	/
75	FRONT BUMPER FOG LAMP RH	CN 701	1	\$ 308.20	\$ 308.20	/
76	FRONT BUMPER FOG LAMP COVER LH	701	1	\$ 113.70	\$ 113.70	/
77	FRONT BUMPER FOG LAMP COVER RH	701	1	\$ 113.70	\$ 113.70	/
78	FRONT BUMPER TOW COVER	17	1	\$ 77.20	\$ 77.20	X
79	FRONT BUMPER LOWER LIP	17	1	\$ 458.30	\$ 458.30	X
80	FRONT BUMPER LOWER RUBBER	17	1	\$ 84.90	\$ 84.90	X
81	FRONT BUMPER GRILLE	CN	1	\$ 166.80	\$ 166.80	/
82	FRONT BUMPER SIDE RETAINER LH	301	1	\$ 89.60	\$ 89.60	/ 102
83	FRONT BUMPER SIDE RETAINER RH	301	1	\$ 89.60	\$ 89.60	/ 60
84	FRONT BUMPER REINFORCEMENT	103	1	\$ 321.70	\$ 321.70	/ 60
85	FRONT BUMPER REINFORCEMENT COVER LH	NS	1	\$ 76.60	\$ 76.60	X
86	FRONT BUMPER REINFORCEMENT COVER RH	NS	1	\$ 76.60	\$ 76.60	X
87	FRONT FENDER LH	17	1	\$ 498.90	\$ 498.90	X
88	FRONT FENDER RH	17	1	\$ 498.90	\$ 498.90	X
89	FRONT FENDER GARNISH LH	17	1	\$ 189.90	\$ 189.90	X
90	FRONT FENDER GARNISH RH	17	1	\$ 189.90	\$ 189.90	X
91	FRONT FENDER SHIELD LH	17	1	\$ 198.20	\$ 198.20	X
Nos.	PARTS		QTY	UNIT \$	Total \$	
FRONT PORTION ONLY						
92	FRONT FENDER SHIELD RH	17	1	\$ 198.20	\$ 198.20	X
93	FRONT FENDER BRACKET LH	17	1	\$ 98.50	\$ 98.50	X
94	FRONT FENDER BRACKET RH	17	1	\$ 98.50	\$ 98.50	X
95	SUPPORT PANEL	301	1	\$ 576.20	\$ 576.20	/
96	SUPPORT PANEL TOP COVER	DE/701	1	\$ 286.20	\$ 286.20	/
97	AIR DUCT	701	1	\$ 97.50	\$ 97.50	/
98	AIR DUCT HOSE	17	1	\$ 35.40	\$ 35.40	X
99	HORN LH	17	1	\$ 98.70	\$ 98.70	X
100	HORN RH	17	1	\$ 98.70	\$ 98.70	X
101	AIRCON CONDENSOR	301/200	1	\$ 950.20	\$ 950.20	/ 810
102	AIRCON CONDENSOR GUIDE LH	17	1	\$ 98.60	\$ 98.60	X
103	AIRCON CONDENSOR GUIDE RH	17	1	\$ 98.60	\$ 98.60	X
104	AIRCON TEMPERATURE SENSOR	17	1	\$ 118.60	\$ 118.60	/
105	RADIATOR	301/200	1	\$ 1,250.70	\$ 1,250.70	/
Total Price					\$ 16,325.48	
Less 20%					\$ 3,265.10	
Sub Total Price					\$ 13,060.38	9812.7

Nos.	PARTS		QTY	UNIT \$	Total \$	REMARKS IF ANY
FRONT PORTION ONLY						
13	FRONT NO. PLATE SET	CN	1	\$ 65.00	\$ 65.00	40
14	BONNET INNER MAT CLIPS SET	17	1	\$ 60.00	\$ 60.00	X
15	GRILLE CLIPS SET	17	1	\$ 50.00	\$ 50.00	X
16	FRONT BUMPER CLIPS SET	17	1	\$ 80.00	\$ 80.00	50
17	FRONT FENDER SHIELD CLIPS SET	17	2	\$ 60.00	\$ 120.00	X
18	SUPPORT PANEL SEALANT	17	1	\$ 80.00	\$ 80.00	X
19	SUPPORT PANEL COVER CLIPS SET	17	1	\$ 50.00	\$ 50.00	X
20	AIR DUCT CLIPS SET	17	1	\$ 20.00	\$ 20.00	✓
21	AIRCON GAS	17	1	\$ 60.00	\$ 60.00	30
22	RADIATOR COOLANT	17	1	\$ 120.00	\$ 120.00	30
Total					\$ 705.00	130

Nos.	Claims Details : Labour and Spray Painting			Total \$	REMARKS IF ANY
FRONT PORTION ONLY					
14	Labour to panel beat/cut/weld affected panels, realign and refit/replace necessary affected parts			\$ 1,600.00	800
15	To putty and spray paint on accident affected portion			\$ 1,400.00	800

16	To disconnect/reconnect and check for proper wiring and electrical function			\$ 100.00	20 40 3100
17	To apply anti rust coating			\$ 120.00	
18	To dismantle and reinstall radiator with high pressure test			\$ 120.00	
19	To dismantle and reinstall aircon condensor with top up gas			\$ 120.00	
Total				\$ 3,460.00	

1760

PARTS TOTAL \$ 28,856.38
 LABOUR TOTAL \$ 9,590.00
OVERALL TOTAL \$ 38,446.38

NAME OF SURVEYOR :

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P 16564.5
 202
 P-13251.6
 S.N-520
 L-4060
 17811.6
 204
 16249