



吉维利企业

KIVILE ENTERPRISE

LKK Auto Consultants here
the Repairer of the following

- To resurvey before/after spray
- To display damaged part(s) during resurvey
- Parts price on a 'Without Prejudice' basis
- Third party insurance claim without prejudice basis
- No illegal or unethical practices
- Customer's satisfaction is our priority
- All work is subject to inspection by the Insurance Company

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: S3T14844X GST REG NO.: M90370110N

Acknowledged by Repairer

Vehicle No: FBQ9850R

Model: Yamaha Aerox155

Date:

Description		
Cover set / Q's	\$	480
Handle Bar / BT	\$	60
Balance / Cut	\$	50
Brake Lever RH / Cut	\$	25
Brake Pump / Cut	\$	180
Headlight / Q's	\$	450
Lamp Stay / ?	\$	160
Fork / ?	\$	360
Fork Lower Cam / ?	\$	180
Mudguard Garnish / Cut	\$	45
Key Cover Garnish / Q's	\$	85
Tank Garnish / mis	\$	85
Tank / BT	\$	280
Dicom Pump / om	\$	360
Side Fairing Garnish 2pc / Cut	\$	120
Foot pedal / Q's	\$	85
Lower Side Garnish RH / RL	\$	45
Radiator / Cut	\$	250
Radiator Cover / Cut	\$	35
Exhaust Pipe / BT	\$	480
Exhaust Pipe Cover / Q's	\$	65
Exhaust Holder / BT	\$	180
Rear Absorber / BT	\$	280
Rear box / mis	\$	145
Rear carrier / Cut	\$	145
Seat / Cut	\$	220
Side cover Garnish / Q's	\$	65
Mirror / Q's	\$	40
Mirror Holder / BT	\$	25
Rear rim / ?	\$	380
Rear rim shift / ?	\$	180
Body Frame Repair / ?	\$	500
Body Frame Respray / ?	\$	280
Seat compartment / Q's	\$	180
Labour	\$	500
Towing	\$	50
IU / Cut	\$	165
TOTAL	\$	7,215

5 Days

Uniform repair

After repair photos

Q's Q's

82880282

13/9/22

4.0