

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMW2828R/2209118

20th September 2022

The Manager
Motor Claim Department
Auto & General Insurance (Singapore) Pte.Limited
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924

Date of Accident : 12th September 2022
Location : Collyer Quay
Third Party Claim Vehicle No : SNA 5829 Y
Repair Cost For Vehicle No : SMW 2828 R Range Rover Velar

Supplementary of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear blind spot radar sensor control module LH 17	1	1,270.50	\$ 1,270.50 X
2	Rear panel air guide LH ene	1	42.50	\$ 42.50 ✓
				\$ 1,313.00

Labour Charges :-

	Amounts
Protective sticker on damage parts	\$ 2,100.00 1800 s/n
Rubberise coating on rear bumper	\$ 300.00 200

Total Amount \$ 3,713.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.