13,877.50

Not Authord 149/22 4/24/500/ 4 days.

SKV8197S Mercedes Benz GLA180

Total parts

					l
1	1	Rear top bumper assy DIS/70.1 12 66.32	\$	1,450.00	
2	1	Rear centre bumper assy De 755-20	\$	1,155.00	
3	1	Rear bumper lower spoiler assy CM 957.25	\$	1,256.00	
4	1	Rear bumper top chrome moulding	\$	297.00	
5	2	Rear bumper side retainer 1	\$	122.00 ×	
6	2	Rear bumper bracket 0/s c/e 60	\$	123.00 (AC	
7	1	Rear bumper reinforcement 3Mf	\$	497.00	
8	1	Rear bumper inner beam 11,	\$	289.00 X	
9	1	Rear bumper tow cover clw hyper	\$	98.00 🗴	
10	1	Rear exhaust chome of Dye	\$	266.00	
11	1	Rear tailgate assy	\$	1,693.00 🗶	
12	1	Rear tailgate centre logo	\$	126.00 🗴	
13	1	Rear tailgate '180' emblem 17	\$	105.00 🗴	
14	1	Rear tailgate 'GLA' emblem	\$	102.00 X	
15	1	Rear tailgate 'cycle and carriage' emblem	\$	106.00 X	
16	1	Rear tailgate lock mechanism ^ ^	\$	282.00 🗶	
17	1	Rear tailgate lock catch	\$	96.00 X	
18	1	Rear tailgate chrome moulding	\$	289.00 ⊁	
9	1	Rear tailgate weatherstrip	\$	288.00 人	
20	1	Rear tailgate inner trim garnish	\$	387.00 🗻	
21	2	Rear no plate lamp	\$	128.00 £	
22	1	Rear right taillamp	\$	875.00 N	
23	1	Rear tailgate right taillamp	\$	793.00	
24	1	Rear right fender outer garnish Dy	\$	475.00	
25	1	Rear end lower panel	\$	1,284.00	
26	1	Rear exhaust heat shield but -	\$	193.00	
		- School Head INICIO 3614	\$	12,775.00	
		less 10%	\$	1,277.50	
		-	\$	11,497.50	
1	LACT	Special Nett Items Rear bumper clips	\$	160.00 60	
2	1	Rear bumper lower spoiler sealant 11	\$	100.00 🗴	
3	1 set	Rear bumper lower spoiler clips	\$	80.00 ×	
4	8	Rear tailgate inner trim garnish clips 1	\$	40.00 ×	
5	4	Rear tailgate outer chrome moulding clips 11	\$	30.00 ×	
			\$		
6	8	Rear right fender inner garnish clips Rear view camera	\$	50.00 × 450.00 X	
7 8		10 . 1	\$	عرا 1,200.00	100
8 9	4	Rear bumper reverse sensor (Shall			118
	1	Rear no plate with garnish Rear and lower panel scalant	\$	100.00	
10	1	Rear end lower panel ton garnish clins 4.0	\$ \$	140.00	
11	4	Rear end lower panel top garnish clips 🔨	\$	30.00 X 2,380.00	

SKV8197S Mercedes Benz GLA180

No		
1	Labour for panel beating, cut, weld, straighten rear affected area and	\$ 1,200.00 50
	replace rear damaged parts.	0-
2	To putty and spray painting rear portion.	\$ 1,200.00
3	To check rear lighting and wiring.	\$ 50.00 20
4	To remove and install rear bootlid lock mechanism.	\$ 10.00 ×
5	To remove and install rear exhaust flange.	\$ 12 80.00 X
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 % 3
7	To apply anti rust proofing to rear affected area.	\$^ 140.00 ×
8	To remove and install rear bumper reverse sensor.	\$ 80.00 \(\ightarrow
9	To remove and install rear view camera.	\$ AA 80.00 X
10	Towing service.	\$ 100.00
	Total labour :	\$ 3,150.00

Total parts: \$ 13,877.50 Total labour: \$ 3,150.00 Total repair cost: \$ 17,027.50

the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: