



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM22008958/Upa3q2 Date: 16/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7098G	Veh. Inspected	SMQ 7512A
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04APD	Excess (\$)	0.00
Assign From		Assign Date	12/09/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA 180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDC1569422J649675	Colour	GREY
Odometer	60104 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	CONTINENTAL	7 mm
L/H Front Tyre	235/50 R18	CONTINENTAL	7 mm
R/H Rear Tyre	235/50 R18	CONTINENTAL	7 mm
L/H Rear Tyre	235/50 R18	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/09/2022	Inspection Date	12/09/2022
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	