



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22008962/Eqy3e2 Date: 08/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 3418K	Veh. Inspected	SLT 1377J
Policy No.		Coverage (\$)	0.00
Claim No.	D22002884MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	12/09/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003573932	Colour	SILVER
Odometer	375291 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	4 mm
L/H Front Tyre	195/65 R15	DUNLOP	4 mm
R/H Rear Tyre	195/65 R15	DUNLOP	4 mm
L/H Rear Tyre	195/65 R15	DUNLOP	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/09/2022	Inspection Date	13/09/2022
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	