

Date: 12/09/2022
 Vehicle No: SNB5287E
 Model: HONDA FIT HYBRID 1.5
 Chassis: GP53117119 - 2014
 Reg.Year: 2015

Not Authored
11 Sep @ 2800h
Passing After Rain
4 days

Third Party Insurer: AIG
 Third Party Veh No: SML5481U
 Date of Accident: 10/09/2022
 Estimator: KIT
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>857.50</i>	1		<i>Pa</i> \$952.50 ✓
2	REAR TAILGATE WINDSCREEN MOULDING	1		<i>na</i> \$137.30 ✓
3	REAR TAILGATE OUTER CHROME GARNISH	1		<i>Pa</i> \$168.90 X
4	REAR TAILGATE "FIT" EMBLEM	1		<i>na</i> \$38.80 ✓
5	REAR TAILGATE "HYBRID" EMBLEM	1		<i>na</i> \$37.50 ✓
6	REAR TAILGATE MECHANISM LOCK	1		<i>na</i> \$110.80 ✓
7	REAR TAILGATE INNER HANDLE COVER	1		<i>Pa</i> \$32.60 X
8	REAR TAILGATE INNER TRIM BOARD	1	<i>my car</i>	\$145.80 ✓
9	REAR TAILGATE WEATHERSTRIP	1		<i>na</i> \$102.30 <i>50% na</i>
10	REAR TAIL LAMP LH	1		<i>Pa</i> \$374.70 X
11	REAR TAIL LAMP RH <i>366.40</i>	1		<i>CM</i> \$374.70 ✓
12	REAR BUMPER <i>521.60</i>	1		<i>na</i> \$703.10 ✓
13	REAR BUMPER SIDE RETAINER LH	1		<i>na</i> \$28.50 X
14	REAR BUMPER SIDE RETAINER RH	1		<i>DI</i> \$28.50 ✓
15	REAR END PANEL TOP GARNISH	1	<i>my car</i>	\$102.20 ✓
16	REAR END PANEL	1		REPAIR
<i>Rec bumper inner bubble CM</i>				<i>892.70</i> ✓
SUB TOTAL				\$3,338.20
LESS 20%				-\$667.64
PARTS TOTAL				\$2,670.56

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		<i>na</i> \$60.00 <i>40% na</i>
2	REAR NUMBER PLATE WITH HOLDER	1		<i>Pa</i> \$50.00 X
3	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>na</i> \$40.00 ✓
4	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
5	REAR BUMPER REVERSE SENSOR	1		<i>Pa</i> \$300.00 X
6	REAR END PANEL TOP GARNISH CLIPS	1		<i>na</i> \$30.00 ✓
S/N TOTAL				\$530.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/09/2022
Vehicle No: SNB5287E
Model: HONDA FIT HYBIRD 1.5
Chassis: GP53117119 - 2014
Reg.Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SML5481U
Date of Accident: 10/09/2022
Estimator: KIT
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST AT ACCIDENT AREA.	\$700.00	500/
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREA.	\$700.00	600/
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS & ETC.	\$150.00	120/
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60/
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	50/
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	20/

LABOUR TOTAL	\$1,850.00
--------------	------------

KIT	TOTAL	\$5,050.56
-----	-------	------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

