

GBB4338R Repair Cost Breakdown

S/N	Description	Cost
S1	Brake Nutker X (BRAKE KNUCKLE) nn	\$ 550.00
S2	Brake Disc Motor X nn	\$ 200.00
S3	Side Sliding Door bt/	\$ 700.00
S4	Front Door bt/	\$ 500.00
S5	(B) Lamp br/	\$ 180.00
S6	Front Lamp or/	\$ 450.00
S7	Air Con Pipe bt/	\$ 550.00
S8	Turbo Tangi bt/	\$ 1,000.00
S9	Turbo Hose cut /	\$ 500.00
S10	Markat X (MUDGUARD) deformed	\$ 300.00
S11	Axel Whole Set X nn	\$ 1,500.00
S12	Towing X	\$ 200.00
S13	Pupler Sub X (PROPELLER SHAFT) nn	\$ 400.00
S14	Tyre x 2 punctured /	\$ 200.00
S15	Resormo (Radiator) Or/	\$ 400.00
S16	Fan Coil (Bowling) deformed	\$ 200.00
S17	Cooling Coil bt/	\$ 200.00
S18	Engine Mounting X nn	\$ 180.00
S19	Gear Box Mounting X nn	\$ 120.00
S20	(F) Gear Oil n/	\$ 60.00
S21	(B) Gear Oil n/	\$ 60.00
S22	Whole Van Respray Painting	\$ 1,000.00
S23	Welding X	\$ 1,500.00
S24	Lower Arm X nn	\$ 300.00
S25	Upper Arm X nn	\$ 400.00
S26	Labour Cost	\$ 2,000.00

4980

252

3735

S/N-320

800

500

2800

1500

\$13,650.00

3735.00

320.00

2800.00

6855.00

20%

5484

45-5500

Rahul

Hp 90010068

10 days

HS

09/09/22 @ 1630

Reg after repair

LKK Auto Consultants hence notify the Requirer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Requirer

Signature:

Date: