

GBB4338R Repair Cost Breakdown

S/N	Description	Cost
S1	Brake Nutker X	\$ 550.00 X
S2	Brake Disc Motor X	\$ 200.00 X
S3	Side Sliding Door bt/	\$ 700.00
S4	Front Door bt/	\$ 500.00
S5	(B) Lamp br/	\$ 180.00
S6	Front Lamp cr/	\$ 450.00
S7	Air Con Pipe bt/	\$ 550.00
S8	Turbo Tangi bt/	\$ 1,000.00
S9	Turbo Hose X	\$ 500.00 X
S10	Markat X	\$ 300.00 X
S11	Axel Whole Set X	\$ 1,500.00 X
S12	Towing X	\$ 200.00 X
S13	Pupler Sub X	\$ 400.00 X
S14	Tyre x 2 performed ✓	\$ 200.00 s/n
S15	Resormo (Radiator) cr/	\$ 400.00
S16	Fan Coil X	\$ 200.00 X
S17	Cooling Coil bt/	\$ 200.00
S18	Engine Mounting X	\$ 180.00 X
S19	Gear Box Mounting X	\$ 120.00 X
S20	(F) Gear Oil m/	\$ 60.00
S21	(B) Gear Oil m/	\$ 60.00
S22	Whole Van Respray Painting	\$ 1,000.00 800
S23	Welding X	\$ 1,500.00 1X
S24	Lower Arm X	\$ 300.00 X
S25	Upper Arm X	\$ 400.00 X
S26	Labour Cost	\$ 2,000.00 1500

4100
252
3075

S/N-200

800 }
2300 }
1500 }

\$13,650.00

3075.00
200.00
2300.00

5575.00

20%
4460

45-84,450

Form
Hp 90010068
10 days
43
09/09/22 @ 1630
Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: