

Date: 12/09/2022

Vehicle No: SLR962L

Model: TOYOTA PRIUS HYBRID 1.8S CVT

Chassis: ZVW506080425-2017

Reg.Year: 2017

Third Party Insurer: ALLIANZ

Third Party Veh No: SMN9496R

Date of Accident: 09/09/2022

Estimator: TING AN

Surveyor:

Not Notarised

11 Rps @ 14,350/p

Assessing After Repair

12 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		Ben \$420.00
2	REAR TAILGATE "PRIUS" EMBLEM	1		Ben \$30.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		Ben \$30.00
4	REAR TAILGATE "TOYOTA" EMBLEM	1		Ben \$55.00
5	REAR TAILGATE OUTER GARNISH COVER	1		Angie M \$330.00
6	REAR TAILGATE INNER TRIM BOARD	1		my DIT \$120.00
7	REAR TAILGATE INNER LOCK	1		Ben \$165.00
8	REAR TAILGATE WEATHERSTRIP	1		DIT \$145.00
9	REAR TAILGATE HANDLE COVER	1		MTI \$18.00
10	REAR WINDSCREEN MOULDING	1		Ben \$40.00
11	REAR BUMPER	1		Ry \$170.00
12	REAR BUMPER LOWER GARNISH COVER	1		CMA \$170.00
13	REAR BUMPER TOWING COVER	1		Ben \$15.00
14	REAR BUMPER ANTENNA SENSOR	1		Ben \$55.00
15	REAR BUMPER SIDE BRACKET LH	1		DIT \$50.00
16	REAR BUMPER SIDE BRACKET RH	1		Ben \$50.00
17	REAR BUMPER REINFORCEMENT	1		Ry \$105.00
18	REAR BUMPER SIDE GARNISH COVER LH	1		MTI \$55.00
19	REAR BUMPER SIDE GARNISH COVER RH	1		Ben \$55.00
20	REAR UPPER TAIL LAMP LH	1		my CMA \$175.00
21	REAR UPPER TAIL LAMP RH	1		Ben \$175.00
22	REAR LOWER TAIL LAMP LH	1		my CMA \$200.00
23	REAR LOWER TAIL LAMP RH	1		Ben \$200.00
24	REAR END PANEL	1		Ry \$215.00
25	REAR END PANEL UPPER COVER	1		Ben \$73.00
26	REAR FLOOR PANEL TOOLBOX TRAY	1		CMA \$530.00
27	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1		Ben \$620.00
28	REAR FENDER INNER TRIM LH	1		De Form \$165.00
29	REAR FENDER INNER TRIM RH	1		Ben \$165.00
30	FRONT BONNET	1		Ben \$230.00
31	FRONT BONNET LOCK	1		DIT \$70.00
32	FRONT BONNET INSULATOR	1		De Form \$165.00
33	FRONT BONNET STAND	1		R \$35.00
34	FRONT BONNET HINGE LH	1		Ry \$40.00
35	FRONT BONNET HINGE RH	1		DIT \$40.00
36	FRONT WIPER AIR GRILLE	1		Ben \$250.00
37	FRONT WIPER WASHER TANK	1		Ben \$72.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/09/2022
 Vehicle No: SLR962L
 Model: TOYOTA PRIUS HYBRID 1.8S CVT
 Chassis: ZVW506080425-2017
 Reg.Year: 2017

Third Party Insurer: ALLIANZ
 Third Party Veh No: SMN9496R
 Date of Accident: 09/09/2022
 Estimator: TING AN
 Surveyor:

38	A-PILLAR GARNISH MOULDING LH	1		nd \$40.00	2
39	A-PILLAR GARNISH MOULDING RH	1		Ph \$40.00	x
40	FRONT HEADLAMP LH	1		cm \$320.00	1
41	FRONT HEADLAMP RH	1		my cm \$320.00	2
42	FRONT BUMPER	1		cm \$165.00	1
43	FRONT BUMPER SIDE BRACKET LH	1		Di \$40.00	1
44	FRONT BUMPER SIDE BRACKET RH	1		Di \$40.00	1
45	FRONT BUMPER TOWING COVER LH	1		nd \$20.00	1
46	FRONT BUMPER TOWING COVER RH	1		Sn \$20.00	x
47	FRONT BUMPER LOWER GRILLE	1		cm \$70.00	1
48	FRONT BUMPER REINFORCEMENT	1		Ry \$215.00	1
49	FRONT BUMPER LOWER REINFORCEMENT	1		Ry \$95.00	2
50	FRONT BUMPER ABSORBER FOAM	1		cm \$50.00	1
51	FRONT BUMPER UNDER COVER	1		cm \$80.00	2
52	FRONT BUMPER FOG LAMP LH	1		Ln \$215.00	x
53	FRONT BUMPER FOG LAMP RH	1		Sn \$215.00	x
54	FRONT GRILLE	1		cm \$110.00	1
55	FRONT GRILLE LOGO EMBLEM	1		nd \$50.00	1
56	FRONT SUPPORT PANEL	1		Ry \$460.00	2
57	FRONT SUPPORT PANEL UPPER COVER	1		nd \$110.00	2
58	FRONT AIR DUCT	1		nd \$35.00	2
59	FRONT AIR FILTER ASSY	1		cm \$320.00	2
60	FRONT HYBRID BATTERY	1		nd \$4,950.00	2
61	FRONT ENGINE ECU	1		Sn \$3,755.00	x
62	ENGINE MOUNTING LH	1		Ph \$90.00	x
63	ENGINE MOUNTING RH	1		Ph \$140.00	x
64	ENGINE MOUNTING REAR	1		Sn \$80.00	x
65	FRONT AIRCON CONDENSER	1		Ry \$550.00	2
66	FRONT AIRCON CONDENSER LIQUID TUBE	1		Sn \$230.00	x
67	FRONT AIRCON CONDENSER PRESSURE PIPE	1		Ln \$135.00	x
68	FRONT RADIATOR	1		Ry \$600.00	2
69	FRONT RADIATOR FAN SHROULD LH	1		cm \$175.00	2
70	FRONT RADIATOR FAN SHROULD RH	1		cm \$175.00	2
71	FRONT RADIATOR FAN BLADE LH	1		Di \$95.00	7
72	FRONT RADIATOR FAN BLADE RH	1		Di \$95.00	7
73	FRONT RADIATOR FAN MOTOR LH	1		Tm \$95.00	2
74	FRONT RADIATOR FAN MOTOR RH	1		Tm \$95.00	2
75	FRONT RADIATOR TOP HOSE	1		Sn \$25.00	x
76	FRONT RADIATOR BOTTOM HOSE	1		Sn \$20.00	x

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/09/2022
 Vehicle No: SLR962L
 Model: TOYOTA PRIUS HYBRID 1.8S CVT
 Chassis: ZVW506080425-2017
 Reg.Year: 2017

Third Party Insurer: ALLIANZ
 Third Party Veh No: SMN9496R
 Date of Accident: 09/09/2022
 Estimator: TING AN
 Surveyor:

77	FRONT FENDER LH	1		<i>Re</i> \$215.00	✓
78	FRONT FENDER RH	1		<i>Re</i> \$215.00	X
79	FRONT FENDER "HYBRID" EMBLEM LH	1		<i>Re</i> \$30.00	✓
80	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>nn</i> \$30.00	X
81	FRONT FENDER INNER SHIELD LH	1		<i>Re</i> \$95.00	X
82	FRONT FENDER INNER SHIELD RH	1		<i>Re</i> \$95.00	X
83	FRONT FENDER GARNISH COVER LH	1		<i>mycra</i> \$50.00	✓
84	FRONT FENDER GARNISH COVER RH	1		<i>Re</i> \$50.00	X
85	FRONT DOOR LH	1		REPAIR	
86	FRONT DOOR RH	1		REPAIR	
				SUB TOTAL	\$20,613.00
				COST +10%	\$2,061.30
				PARTS TOTAL	\$22,674.30

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR WINDSCREEN SEALANT	1		<i>Re</i> \$80.00	✓
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>Re</i> \$50.00	✓
3	REAR BUMPER REVERSE SENSOR	1		<i>Re</i> \$300.00	20000
4	REAR BUMPER CLIPS	1		<i>Re</i> \$50.00	✓
5	REAR REVERSE CAMERA	1		<i>Sen</i> \$150.00	X
6	REAR NUMBER PLATE & HOLDER	1		<i>Re</i> \$50.00	4500
7	REAR END PANEL JOINT SEALANT	1		<i>Re</i> \$100.00	3000
8	REAR END PANEL UPPER COVER CLIPS	1		<i>Re</i> \$40.00	✓
9	REAR FENDER INNER TRIM CLIPS LH	1		<i>Re</i> \$50.00	✓
10	REAR FENDER INNER TRIM CLIPS RH	1		<i>nn</i> \$50.00	X
11	FRONT BUMPER CLIPS	1		<i>Re</i> \$50.00	✓
12	FRONT BONNET INSULATOR CLIPS	1		<i>Re</i> \$40.00	✓
13	FRONT SUPPORT PANEL UPPER COVER CLIPS	1		<i>Re</i> \$40.00	✓
14	FRONT NUMBER PLATE & HOLDER	1		<i>mi</i> \$50.00	4500
15	FRONT BATTERY	1		<i>Re</i> \$180.00	✓
16	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>nn</i> \$40.00	X
17	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>nn</i> \$40.00	X
18	RADIATOR COOLANT	1		<i>Re</i> \$80.00	5000
				S/N TOTAL	\$1,440.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/09/2022
Vehicle No: SLR962L
Model: TOYOTA PRIUS HYBRID 1.8S CVT
Chassis: ZVW506080425-2017
Reg.Year: 2017

Third Party Insurer: ALLIANZ
Third Party Veh No: SMN9496R
Date of Accident: 09/09/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR & FRONT ACCIDENT AREAS & ETC.

1200
\$2,500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR TAILGATE OUTER GARNISH COVER, REAR BUMPER, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

1800
\$2,000.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

\$150.00 ✓

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$120.00 60

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 50

TO REFILL AIRCON GAS & ETC.

\$150.00 100

TO TUFF KOTE & UNDERSEAL MATERIALS & ETC.

\$150.00 120

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 100

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$100.00 80

LABOUR TOTAL \$5,420.00

TING AN

TOTAL \$29,534.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 21/09/2022
Vehicle No: SLR962L
Model: TOYOTA PRIUS HYBRID 1.8S CVT
Chassis: ZVW506080425-2017
Reg.Year: 2017

Third Party Insurer: ALLIANZ
Third Party Veh No: SMN9496R
Date of Accident: 09/09/2022

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT STAY PANEL	1		R ₁ \$38.00
2	FRONT HEADLAMP UPPER PANEL LH	1		R ₂ \$95.00
3	FRONT BATTERY TERMINAL	1		M \$65.00
4	FRONT BUMPER LOWER AIR DUCT	1		DJ \$160.00
5	FRONT BUMPER LOWER AIR DUCT	1		CNY \$600.00
	REAR WINDSCREEN GLASS	1		CRA 300.00
	Part headlamp control unit			
SUB TOTAL				\$958.00
COST +10%				\$95.80
PARTS TOTAL				\$1,053.80

TING AN TOTAL \$1,053.80

Head office

8 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

