

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 12.09.2022

TO : **UOI** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMS8289C**
MODEL : **MERCEDES BENZ A200**
DATE OF ACCIDENT : 29.08.2022
TIME OF ACCIDENT : 13:50 HRS

WDD17718724012382
Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>new Rehd</i>	1	\$ 1,691.00	\$ 1,691.00
2	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 148.00	\$ 296.00
3	HEAD LAMP LH <i>new</i>	1	\$ 3,154.00	\$ 3,154.00
4	FRONT FENDER LH <i>Dented</i>	1	\$ 1,102.00	\$ 1,102.00
5	FRONT FENDER COWLING LH (FRONT) <i>new</i>	1	\$ 228.00	\$ 228.00
6	FRONT DOOR LH <i>Dented</i>	1	\$ 2,584.00	\$ 2,584.00
7	FRONT DOOR CHROME MOULDING LH <i>new</i>	1	\$ 227.00	\$ 227.00
8	FRONT DOOR OUTER HANDLE LH <i>new</i>	1	\$ 228.00	\$ 228.00
9	FRONT DOOR SIDE MIRROR LH <i>new</i>	1	\$ 1,007.00	\$ 1,007.00
10	FRONT DOOR SIDE MIRROR HOUSING LH <i>new</i>	1	\$ 275.00	\$ 275.00

5340
4806

TOTAL PRICE \$ 10,792.00
LESS 10% \$ 1,079.20
SUB TOTAL PRICE \$ 9,712.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
2	FRONT BUMPER BOTTOM GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
3	FRONT FENDER COWLING CLIPS(SET) <i>new</i>	1	\$ 80.00	\$ 80.00
4	FRONT DOOR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00
5	FRONT DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
6	FRONT DOOR SIDE MIRROR COVER (SPECAL TYPE) <i>new</i>	1	\$ 550.00	\$ 550.00

280

TOTAL \$ 1,070.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	600

TO : **UOI** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMS8289C**
MODEL : **MERCEDES BENZ A200**
DATE OF ACCIDENT : 29.08.2022
TIME OF ACCIDENT : 13:50 HRS

2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	800
3	WIRING CHECK	\$ 150.00	30
4	REFOCUS HEADLAMP BEAM	\$ 60.00	X
5	REMOVE AND REFIX FRONT DOOR GLASS	\$ 80.00	40
6	REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 80.00	40
7	REMOVE AND REPLACE FRONT BUMPER SENSOR	\$ 120.00	50
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 600.00	X

TOTAL \$3,890.00

TOTAL PARTS COST : \$ 10,782.80
TOTAL LABOUR COST : \$ 3,890.00
TOTAL REPAIR COST : \$ 14,672.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian Ly
L/S 13/09/22

05 Days.

total 6646

L/S 5.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: