



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/10/2022
User ID : PohSuan
Section A - Accident Details

Registration Number	SHD6174B
Case Reference Number	TAX/09/22/2025
Registration Date	6/5/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHONG CHEE WAI
Type of Accident	Side Swipe
Accident Date and Time	10/9/2022 12:30 PM
Accident Reported Date and Time	12/9/2022 11:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116224
Special Instruction to ARC, if any	DAMAGE TO THE LEFT SIDE MIRROR
Prepared Date and Time	12/9/2022 1:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$50.00
Total Spray Cost	\$180.00	\$50.00
Total Spare Part Cost	\$1,538.86	\$113.19
Total Other Cost	\$380.00	(\$13.19)
TOTAL COST	\$2,436.86	\$200.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	1.0
Prepared / Adjusted By	Boon Chew Tay	Rasul (LKK) / AXA
ARC / Surveyor Sign Off Date	13/09/2022 5:39 PM	13/09/2022 4:56 PM
Signature		
Remarks	Lump sum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2210-0005	Invoice Number	
Quotation Date	03.10.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$338.00	\$50.00 ✓
Total Labour	\$338.00	\$50.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00 ✓
Total Spray Painting & Panel Beating	\$180.00	\$50.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$53.19) 0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	(\$13.19)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87940-47310	MIRROR ASSY, LH	0.00	\$1,399.60	0.00	\$0.00	Replace	Not Given
		87961-47150	MIRROR GLASS LH	1.00	\$161.70	30.00	\$113.19	Replace	Replace
		81740-52040	MIRROR LAMP LH	0.00	\$73.80	0.00	\$0.00	Replace	Not Given
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$142.30	100.00	\$0.00	Replace	Repair
Total					\$1,777.40		\$113.19		

X NN
✓ CRA
X NN
R X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	113.19	
+	50.00	
+	90.00	L/S \$200/-
	253.19	
	-20%	
	202.55	