



Section A - Accident Details

Registration Number	SHF33D
Case Reference Number	TAX/09/22/2027
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN WEE MENG
Type of Accident	Side Swipe
Accident Date and Time	12/9/2022 4:34 PM
Accident Reported Date and Time	13/9/2022 10:36 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116256
Special Instruction to ARC, if any	TP/LEFT FRONT PORTION
Prepared Date and Time	13/9/2022 10:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$5,955.38	\$756.69
Total Other Cost	\$500.00	\$60.00
TOTAL COST	\$8,247.38	\$1,516.69 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	13/09/2022 5:35 PM	13/09/2022 5:01 PM
Signature		
Remarks	parts by parts / Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2210-0022	Invoice Number	
Quotation Date	05.10.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$300.00 ✓
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
RESPRAY WHEEL CAP	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53852-47041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given
		53857-12010	RETAINER, FR WHEEL LH	1.00	\$3.50	25.00	\$2.63	Replace	Replace
		53876-47060	LINER, FR FENDER, LH	0.00	\$227.80	0.00	\$0.00	Replace	Not Given
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair
		81185-47890	UNIT, HEADLAMP, LH	0.00	\$2,852.40	0.00	\$0.00	Replace	Check
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$103.70	25.00	\$77.78	Replace	Replace
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52128-47910	COVER, FR BUMPER LH	0.00	\$32.70	0.00	\$0.00	Replace	Not Given
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$86.20	0.00	\$0.00	Replace	Check
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	Replace
		42611-47450	WHEEL, DISC FRONT	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	Replace
Total					\$7,326.80		\$756.69		

X NN
✓ NEC
X NN
✓ NEC
R
X NN
✓ SCR
✓ NEC
X
X
✓ SCR
X
✓ SCR

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

756.69
+ 300.00
+ 460.00
1,516.69