

9/13/22, 5:07 PM


<https://vacweb.smrt.com.sg/Estimation.aspx>

Case Details

Case Reference Number : TAX/09/22/2027
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF33D

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19350-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 12/09/2022 08:34 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	555.60	555.60	25.00	424.20	Replace	1	424.20 ✓	Replace ▾	sol ✓
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check ▾	? Xan
One Time Key In	Main			COVER, FR BUMPER LH	1	32.70	32.70	25.00	24.53	Replace	0	0	Not Give ▾	Xan
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00 ✓	Replace ▾	new ✓
One Time Key In	Main			MOULDING, FRONT BUMPER SIDE, LH	1	103.70	103.70	25.00	77.78	Replace	1	77.78 ✓	Replace ▾	sol ✓
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	0	0	Check ▾	? Xan
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	1,060.70	1,060.70	25.00	795.53	Replace	1	0	Repair ▾	R
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	25.00	44.33	Replace	1	44.33 ✓	Replace ▾	new ✓
One Time Key In	Main			LINER, FR FENDER, LH	1	227.80	227.80	25.00	170.35	Replace	0	0	Not Give ▾	Xan
One Time Key In	Main			RETAINER, FR WHEEL LH	1	3.50	3.50	25.00	2.63	Replace	1	2.63 ✓	Replace ▾	new sol ✓

Total Spare Part Cost 6,955.38

Lump Sum Discount (%) 0.00

Final Spare Part Cost 6,955.38

Surveyor Total 756.69

Lump Sum Dis (%) 0

Final Sur Total 756.69

<https://vacweb.smrt.com.sg/Estimation.aspx>

9/13/22, 5:07 PM

<https://vacswb.smrt.com.sg/Estimation.aspx>

https://vacswb.smrt.com.sg/Estimation.aspx

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PAD, FR WHEEL LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Give ▾	Xm
One Time Key In	Main			WHEEL, DISC FRONT	1	2,036.30	2,036.30	25.00	1,527.22	Replace	0	0	Not Give ▾	Xm
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	229.00	229.00	25.00	171.75	Replace	1	171.75	Replace ▾	sur ✓
Total Spare Part Cost									5,955.38		Surveyor Total		766.69	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									5,955.38		Final Sur Total		756.69	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	676.00	300.00	
Total:			676.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
3	Main	RESPRAY WHEEL CAP	180.00	0	Xm
4	Main	TO RESPRAY RIM	180.00	0	Xm
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	Xm
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	Xm
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	Xm
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00	
Total:			500.00	60.00	


<https://vacswb.smrt.com.sg/Estimation.aspx>

9/13/22, 5:07 PM

<https://vacswb.smrt.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>XIN</i>	
Total:			500.00	60.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,955.38	755.69
Total Labour Cost	676.00	300.00
Total Spray Painting	1,116.00	400.00
Other	500.00	60.00
Overall Total	8,247.38	1,516.69
Lump Sum Repair Option	☒	☐
Lump Sum Total	0.00	1,516.69
Surveyor Approved Amount		1,516.69
No of Repair Days*	5	3
Remarks	-	parts by parts / Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SUPERVISOR, BASIL, 0901 0001 0001
Surveyor Name		Rasul
Signature		
Survey Date	13/09/2022	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: