

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCA83U

OD/GA

M/S: GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037

FAX: 62353354

ATTN: Motor Claim Department

Claim No: ES2290934

Estimate No: ES2290934/YISHUN

Date: 13 Sep 2022

Policy No: MOMVP000004867-00-00

Veh Reg No: SCA83U.1

Make/Model: HONDA HONDA VEZEL
1.5X CVT

Chassis No: RU11203716

Engine No: L15B4403716

Reg. Date: 27/12/2016

WS Ref: OD/GA

Claim Type: Own Damage

Accident Date: 09/09/2022

Not Notified

11 Pump B

Running After Rain

Ex TBA

Estimate Repair Cost to Vehicle No : SCA83U.1

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Cost Plus				
1 FRONT BUMPER	210.00	1 PC	210.00	✓
2 FRONT BUMPER LOWER GRILLE	55.00	1 PC	55.00	✓
3 FRONT BUMPER LOWER SKIRT	130.00	1 PC	130.00	✓
4 FRONT BUMPER LH FOG LAMP GARNISH	15.00	1 PC	15.00	✓
5 FRONT BUMPER RH FOG LAMP GARNISH	15.00	1 PC	15.00	x
6 FRONT BUMPER REINFORCEMENT	178.00	1 PC	178.00	✓
7 FRONT BUMPER REINFORCEMENT TOP TRIM LH	18.00	1 PC	18.00	✓
8 FRONT BUMPER REINFORCEMENT TOP TRIM RH	18.00	1 PC	18.00	✓
9 FRONT BUMPER REINFORCEMENT TOP TRIM CLIPS	2.00	6 PCS	12.00	✓
10 FRT SUPPORT PANEL	290.00	1 PC	290.00	✓
11 FRONT GRILLE UPPER	160.00	1 PC	160.00	✓
12 FRONT GRILLE EMBLEM	15.00	1 PC	15.00	✓
13 FRONT GRILLE CHROME MOULDING	50.00	1 PC	50.00	✓
14 FRONT GRILLE CLIPS	2.00	4 PCS	8.00	✓
15 FRONT GRILLE LH BRACKET	12.00	1 PC	12.00	?
16 FRONT GRILLE RH BRACKET	12.00	1 PC	12.00	?
17 LH HEADLAMP	920.00	1 PC	920.00	✓
18 RH HEADLAMP	920.00	1 PC	920.00	✓
19 HEADLAMP LOWER BRACKETS	24.00	2 PCS	48.00	✓
20 FRONT LH FENDER ARCH TRIM	50.00	1 PC	50.00	?
21 FRONT RH FENDER ARCH TRIM	50.00	1 PC	50.00	x
22 BONNET	390.00	1 PC	390.00	✓
23 BONNET LOCK	65.00	1 PC	65.00	✓
24 BONNET FRONT RUBBER SEAL LH	15.00	1 PC	15.00	?
25 BONNET FRONT RUBBER SEAL RH	15.00	1 PC	15.00	?
26 BONNET SIDE RUBBER SEAL LH	16.00	1 PC	16.00	?
27 BONNET SIDE RUBBER SEAL RH	16.00	1 PCS	16.00	?
28 BONNET INSULATOR CLIPS	2.00	6 PCS	12.00	✓
29 BONNET HINGES	30.00	2 PCS	60.00	✓
30 BONNET LOCK BRACKET	24.00	1 PC	24.00	✓
31 BONNET LOCK BRACKET CLIPS	2.00	4 PCS	8.00	✓
32 FRONT AIR DUCT CLIPS	2.00	4 PCS	8.00	✓
33 FRONT SUPPORT TOP COVER	50.00	1 PC	50.00	x
34 FRT SUPPORT TOP COVER CLIPS	2.00	8 PCS	16.00	✓
35 AIR-CON CONDENSER	320.00	1 PC	320.00	?
36 HORN	45.00	1 PC	45.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037 FAX: 62353354

ATTN: Motor Claim Department

WS Ref: OD/GA
Claim Type: Own Damage
Accident Date: 09/09/2022

Claim No: ES2290934
Estimate No: ES2290934/YISHUN
Date: 13 Sep 2022
Policy No: MOMVP000004867-00-00
Veh Reg No: SCA83U.1
Make/Model: HONDA HONDA VEZEL
1.5X CVT
Chassis No: RU11203716
Engine No: L15B4403716
Reg. Date: 27/12/2016

Estimate Repair Cost to Vehicle No : SCA83U.1

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
			4,246.00	
	Add 10%		424.60	4,670.60
Special Net				
37 FRONT NUMBER PLATE	35.00	1 PC <i>cm</i>	35.00 ✓	35.00
Labour				
38 REMOVE DAMAGED PARTS & ATTACHMENTS,PANEL BEAT & REPAIR FRT FENDERS,FRT SUPPORT PANEL,SIDE INNER FRAME PANELS	850.00	1 LA	850.00 <i>600</i>	
39 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00 ✓	
40 PAINTING - FRT BUMPER,BONNET,HINGES,FRT FENDERS,SUPPORT PANEL,INNER PANEL,FRT BUMPER REINFORCEMENT	900.00	1 LA	900.00 <i>800</i>	
				1,850.00
Total				S\$ 6,555.60
Add GST @ 7%				458.89
Total Amount payable				<u>S\$ 7,014.49</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE