

# AUTOWERKS

## ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
 #08-1339 Singapore 470130  
 Tel: 9450 7920  
 \* zoomautowerks@gmail.com

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

15 September 2022

*Mr Andrew*

*14/9/22*

*6 days 2/5 @ 4500*

REG NO.: GX 646 C  
 MAKE/MODEL: TOYOTA LITEACE

Acknowledged by Repairer  
 Signature:  
 Date:

### ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding <i>neu</i>	\$ 130.50 /
1	Rear tailgate <i>body 1615.20</i>	\$ 1,793.50 /
2	Rear tailgate dampers <i>11</i>	\$ 508.40 X
1	Rear tailgate inner board <i>to in</i>	\$ 286.95 /
1	Rear tailgate lock <i>to / neu</i>	\$ 223.30 /
1	Rear tailgate lock catch <i>11</i>	\$ 65.90 X
1	Rear tailgate outer garnish <i>11</i>	\$ 219.20 X
1	Rear tailgate rubber <i>11</i>	\$ 328.48 /
2	Rear taillamps <i>1/5 crb 0/5 an 385.50</i>	\$ 771.00 / <i>pc</i>
1	Rear taillamp panel -LH <i>1/5 408.50</i>	\$ 461.90 /
1	Rear bumper <i>1/5 488.61</i>	\$ 695.20 /
2	Rear bumper brackets <i>neu</i>	\$ 57.20 /
2	Rear bumper reflectors <i>11</i>	\$ 130.00 X
2	Rear bumper side retainers <i>11</i>	\$ 132.40 /
1	Rear end panel <i>1/5 680.50</i>	\$ 887.90 /
1	Rear end panel top moulding <i>neu</i>	\$ 108.60 X
2	Rear number plate lamps <i>11</i>	\$ 136.00 X
1	Rear side body panel -LH <i>R</i>	\$ 1,765.50 X
		\$ 8,701.93
	Less 25%	\$ 2,175.48
		\$ 6,526.45

### SPECIAL NETT ITEMS

1	Rear windscreen sealant <i>neu</i>	\$ 80.00 <i>40</i>
1	Rear bumper clip (1 set) <i>neu</i>	\$ 50.00 /
1	Rear tailgate "70KM/H" sticker <i>neu</i>	\$ 25.00 <i>10</i>
1	Rear tailgate "5PAX" sticker <i>neu</i>	\$ 25.00 <i>10</i>
1	Rear reverse sensor (1 set) <i>neu NF</i>	\$ 350.00 X
		\$ 530.00

### LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>30</i>
2	To remove and refit inner garnishes.	\$ 150.00 X
3	To remove and refit rear reverse sensor.	\$ 120.00 X
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 80.00 <i>60</i>
5	To remove and refit rear windscreen glass.	\$ 180.00 <i>120</i>
6	To apply undercoating.	\$ 180.00 <i>80</i>
7	Panel beating.	\$ 1,600.00 <i>900</i>
8	To re-spray painting on the affected areas.	\$ 1,500.00 <i>800</i>
		\$ 3,890.00

GRAND TOTAL :

*3-470846*  
*252*  
*3531.34*  
*110 1990*

\$ 10,946.45