



Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/092022/5630
Date : 12-09-2022
Accident Date : 27-08-2022

Vehicle Details

Make & Model : Mercedes Benz GLC200 (R18 LED)
Chassis No : WDC2539422F459760
Registration No : SMC7473C


Third Party Vehicle Details

Registration No : SMF1140L

S/N	Description	Qty	Amount (\$\$)
1	LH HEADLAMP X NN	1.00	\$3,420.00
2	FRONT BUMPER ✓ BR	1.00	\$1,359.00
3	FRONT BUMPER LH FOG LAMP COVER X NN	1.00	\$84.00
4	FRONT BUMPER CENTRE LOWER GRILLE X NN	1.00	\$345.00
5	FRONT CENTRE LOWER GRILLE CHROME ✓ CRA	1.00	\$675.00
6	FRONT BUMPER LH SIDE RETAINER X NN	1.00	\$72.00
7	FRONT BUMPER LH LOWER PAD X NN	1.00	\$214.00
8	FRONT BUMPER LH PARKING SENSOR ✓ CUT	1.00	\$288.00
9	FRONT BUMPER PARKING SENSOR X NN	2.00	\$576.00
10	FRONT BUMPER SPONGE ✓ CRA	1.00	\$171.00
11	FRONT BUMPER REINFORCEMENT ✓ BT	1.00	\$435.00
12	FRONT BUMPER CLIPS ✓ NEC	10.00	\$90.00
13	FRONT LH WHEEL ARCH GARNISH ✓ BR	1.00	\$246.00
			\$7,975.00
Discount: -10%			(\$797.50)
			\$7,177.50
14	TO RESET HEADLAMP SYSTEM XNN	1.00	\$280.00
15	TO REPAIR DAMAGES	1.00	\$580.00 250
16	TO SPRAY PAINTING	1.00	\$680.00 280
Subtotal w/o GST:			\$8,717.50

Issued by Raymond Teo

This is a computer-generated document. No signature is required.



3 Days

P/P

Guo Qiang

13/09/2022