

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008996/UCY3Q2**Date:** 16/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00214412101

**Claimant Vehicle
No :** SMQ3734C**Insured Vehicle
No :** SLS2028R

Date of Loss: 12/09/2022

Nature of Claim: TP

Claim
No: SNM22D206525/C02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ3734C**

Make & Model: TOYOTA PRIUS PLUS, 1.8 (A)

Engine No: 2ZR0E80576

Reg. Date: 13/11/2019 (Man. Year: 2019)

Chassis No: JTDZS3EU60J052175

Colour: White

Odometer: 268340 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,570.00	1,700.00	870.00	33.85
Miscellaneous Items	280.00	200.00	80.00	28.57
Labour	1,159.48	1,029.28	130.20	11.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,009.48	2,929.28	1,080.20	26.94
+ GST 7.00/7.00% (S\$)	280.66	205.05	75.61	26.94
Nett Amount (S\$)	4,290.14	3,134.33	1,155.81	26.94

INSPECTION

Date of Assignment: 15/09/2022 Present Location: Jin Auto Services Pte Ltd (Defu)

Date Inspected: 14/09/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)

Estimated Period of Repair: 4.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2022)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ3734C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		2,570.00 F	*1,700.00 F
F=Franchise part.						
Total Parts (\$\$)					2,570.00	1,700.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	TOTAL EXTRA	280.00	200.00
Sub Total (\$)			280.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL PAINT	New	676.48	676.48
2	TOTAL LABOUR	New	483.00	352.80
Gross Labour Cost (\$)			1,159.48	1,029.28

Report was unsubmitted during this print-out.

< END OF ESTIMATES >