

Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 22/09/2022

Survey details

| | |
|---------------------|---------------------|
| Date of loss | 9/9/2022 |
| Date of appointment | 13/9/2022 |
| Date of survey | 13/9/2022 |
| Location of survey | V TECH AUTO SERVICE |

Vehicle Details:

| | |
|----------------------|---------------------------------------|
| Claim Type: | THIRD PARTY |
| Vehicle number | SKT 1294B |
| Make and Model | MERCEDES BENZ B180 STYLE (R16 LED SR) |
| Date of registration | 25/5/2015 |
| Excess | |
| Market Value | \$53,000.00 |
| Parf Rebate | \$28,228.00 |
| Nett Loss | \$24,772.00 |

Repair details

| | |
|------------------|--|
| Initial Estimate | |
|------------------|--|

Proposed/Revised repair cost:

| | |
|--------------------------|--------------|
| Parts | |
| "Check items (Estimated) | |
| Labour | |
| Total | |
| Lump Sum (Estimated) | |
| | |
| Number of days of repair | 4 days (est) |

Remarks:

Damages Consistent.

The estimate repair cost of the damaged vehicle is in the region of \$3,000.00 to \$4,000.00