

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, being resurveyed
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged

14/9/22

4/5 @ 3800 / 4 days

Date, 13/9/2022
Nett item

1	IPC Front door nls	DI/hurf	\$ 1090.30	/
2	IPC Front door w/strip nls	ner	\$ 134.40	/
3	IPC Rear door nls	ner	\$ 1090.30	/
4	IPC Rear door w/strip nls	ner	\$ 134.40	/
5	IPC Rear door inner lock nls	ner	\$ 198.30	X
6	IPC Rear door outer handle nls	ner	\$ 94.70	X
7	IPC Rear door top outer moulding nls	ner	\$ 166.20	/
8	IPC Rear door regulator gear nls	ner	\$ 103.40	/
9	IPC Rear fender garnish nls	ner	\$ 160.50	/
Less			\$ 3172.50	
10%			\$ 951.80	
			\$ 2220.70	

S/Nett Item:-

IPC Rear wheel rim nls R \$ 485.00 X

Labour charges:-

1	To remove, replace front & rear door.	\$ 780.00	500
2	To spray painting	\$ 780.00	700
Total		\$ 4265.70	

10	1 pc Front door protector nls	\$ 213.00	garn
11	1 pc Rear door protector nls	\$ 130.40	garn
12	1 pc Rocker garnish nls	\$ 737.00	garn

P-3989.9

102
3563.91
1200

10%

5872.61