



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM22009001/Apa3q2 Date: 19/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBW 1888D	Veh. Inspected	SMX 8554K	
Policy No.	GA501650	Coverage (\$)	0.00	
Claim No.	S2M04AVP	Excess (\$)	0.00	
Assign From		Assign Date	13/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESQUIRE HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZWR800356472	Colour	WHITE	
Odometer	160390 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	PETLAS	6 mm	
L/H Front Tyre	215/50 R17	PETLAS	6 mm	
R/H Rear Tyre	215/50 R17	PETLAS	6 mm	
L/H Rear Tyre	215/50 R17	PETLAS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/09/2022	Inspection Date	13/09/2022	
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	