

TP Gmb
Veron

SJZ9259G. 2011 Jan.

Mercedes Benz E250. 1796cc.

WDD2120472A359311

Rees Byper ^{Del'd} 1640.60. ✓

Rees Byper Clips. ^m 50(SN) ✓

Rees Byper Side Holder RH. ^{Del'd} 58.40. ✓

Rees Byper Tow Cover ^{Del'd} 55.90. ✓

Rees Byper lower Garnish. ^{Del'd} 485.10. ✓

Rees Byper Reinforcement. ^{Del'd} 765. ✓

Rees Byper Centre Guide. ^{Del'd} 211.80. ✗

Reverse Sensor x02 ^{2pk} ~~255x2 = 510~~ 510

Tailgate RH ^{Del'd} 672.50. ✓

Tailgate lower Bracket RH. ^{Del'd} 68.10. ✓

Rees Fender Air Vent. ^m 72.90 ✗

425560

S.N. 50

3830-04

SJZ92596.

Panel Benty

~~500~~ 300

Spry Painting.

~~500~~ 250

630

~~50~~ 30

Wiring.

150 x

To spray tuff coat.

~~100~~ 50.

To remove reverse sensor

total: 4510.04

L/S: 3.6K.

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.6K.