

AIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 13 Sep 2022)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	ComfortDelGro Engineering Pte Ltd/SHC3089P/13/09/2022 14:57		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TRUNK LID COVER	25.00	0.00 <i>ht</i>	*1,303.29 FL
2	1		*GARNISH SUB - ASSY BACK DOOR OUTSIDE	25.00	0.00 <i>ht</i>	*1,054.71 FL
3	1		*TRUNK LID EMBLEM - PRIUS	25.00	0.00 <i>ht</i>	*62.14 FL
4	1		*TRUNK LID EMBLEM - HYBRID	25.00	0.00 <i>ht</i>	*62.14 FL
5	1		*TRUNK LID EMBLEM - TOYOTA STAR	25.00	0.00 <i>ht</i>	*81.43 FL
6	1		*TRUNK LID REAR WINDSCREEN GLASS (BIG)	25.00	0.00 <i>ht</i>	*805.80 FL
7	1		*TRUNK LID REAR WINDSCREEN GLASS (SMALL)	25.00	0.00 <i>ht</i>	*1,758.70 FL
8	1		*TRUNK LID REAR WINDSCREEN GLASS MOULDING	25.00	0.00 <i>ht</i>	*40.40 FL
9	1		*REAR BUMPER ASSY	25.00	0.00 <i>ht</i>	*503.04 FL
10	10		*REAR BUMPER CLIPS	25.00	0.00 <i>ht</i>	*22.00 FL
11	1		*REAR BUMPER BEAM	25.00	0.00 <i>ht</i>	*378.32 FL
12	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00 <i>ht</i>	*654.96 FL
13	1		*COVER FLOOR UNDERCOVER	25.00	0.00 <i>ht</i>	*220.50 FL
14	1		*REAR BUMPER TOW COVER	25.00	0.00 <i>ht</i>	*82.70 FL
15	1		*REAR BUMPER MAT	0.00	0.00 <i>ht</i>	*50.00 F
16	1		*REVERSE SENSOR	0.00	0.00 <i>ht</i>	*135.70 F
17	1		*TAILLAMP ASSY UPPER LH	25.00	0.00 <i>ht</i>	*557.90 FL
18	1		*TAILLAMP ASSY LOWER LH	25.00	0.00 <i>ht</i>	*570.00 FL
19	1		*REAR END PANEL	25.00	0.00 <i>ht</i>	*738.96 FL
20	1		*REAR END PANEL GARNISH	25.00	0.00 <i>ht</i>	*165.80 FL nn
21	1		*REAR NUMBER PLATE	0.00	0.00 <i>ht</i>	*50.00 F
22	2		*WINDSCREEN SEALANT	0.00	0.00 <i>ht</i>	*46.00 F
23	1		*REAR BUMPER SIDE BRACKET LH	25.00	0.00 <i>ht</i>	*94.80 FL nn
24	1		*SEAL REAR BUMPER SIDE LH	25.00	0.00 <i>ht</i>	*148.40 FL nn

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	9,587.69
- List Item Discount on L Items (\$)	2,326.50
Total Parts (\$)	7,261.19

ComfortDelGro Engineering Pte Ltd/SHC3089P/13/09/2022 14:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

8158.03
25% 6118.52
SN 281.70.

Estimates on Miscellaneous Items

Repairer Estimates

Miscellaneous Items

Qty	Particulars	Amount
1	1 OD/TP Case (Insurer)	11.00
Sub Total (S\$)		11

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 1,400.00
2	SPRAYPAINT	New	750 1,000.00
3	TUFF KOTE	New	30 50.00
4	CHECK WIRING	New	30 50.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	✓ 120.00
6	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
7	TOWING FEE	New	✓ 60.00
Gross Labour Cost (S\$)			1720 2,730.00

ComfortDelGro Engineering Pte Ltd/SHC3089P/13/09/2022 14:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6118.52
 281.70
 11
 1720
 8131.22
 1596500
 4 days
 #

Tanpin 97495747
 ins' 14/9/22 @ 1025
 1/3 Body after repair
 3-4 days
 Tanpin @ 11/10/22

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: