

AGS. REC'D BY: Taufik

REF: CS/TM122009007/July 3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLR 1305C

Policy No. MN000276

Claims No. M2205002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Merimen Vehicle: IN / OUT

Veh No: SHC 3089P

Yr Regn: 2019, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

C.C. 1798

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 545997

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD KB3F4 603079848

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/9/2022

D.O.I. 14/9/22

Survey held at Confort Loggia

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/9/22 Taufik informed LS \$6500 (Red 3502.19, 35%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 23/9/22-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / L.B. / C. LS \$6500

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

Jumani
(LIS)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/09/2022
Vehicle Reg. No.:	SHC3089P	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	01/04/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2C06300	Chassis No:	JTDKB3FU603079848
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	7,261.19
Miscellaneous Items	11.00
Labour	2,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,002.19
+ GST 7.00% (S\$)	700.15
Nett Amount (S\$)	10,702.34

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2022)**Parts:** 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3089P/13/09/2022 14:57**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TRUNK LID COVER	25.00	0.00	bt *1,303.29 FL
2	1		*GARNISH SUB - ASSY BACK DOOR OUTSIDE	25.00	0.00	org *1,054.71 FL
3	1		*TRUNK LID EMBLEM - PRIUS	25.00	0.00	net *62.14 FL
4	1		*TRUNK LID EMBLEM - HYBRID	25.00	0.00	net *62.14 FL
5	1		*TRUNK LID EMBLEM - TOYOTA STAR	25.00	0.00	net *81.43 FL
6	1		*TRUNK LID REAR WINDSCREEN GLASS (BIG)	25.00	0.00	net *805.80 FL
7	1		*TRUNK LID REAR WINDSCREEN GLASS (SMALL)	25.00	0.00	net *1,758.70 FL
8	1		*TRUNK LID REAR WINDSCREEN GLASS MOULDING	25.00	0.00	net *40.40 FL
9	1		*REAR BUMPER ASSY	25.00	0.00	cur *503.04 FL
10	10		*REAR BUMPER CLIPS	25.00	0.00	net *22.00 FL
11	1		*REAR BUMPER BEAM	25.00	0.00	bt *378.32 FL
12	1		*REAR BUMPER CENTRE MOULDING	25.00	0.00	del *654.96 FL
13	1		*COVER FLOOR UNDERCOVER	25.00	0.00	del *220.50 FL
14	1		*REAR BUMPER TOW COVER	25.00	0.00	mis *82.70 FL
15	1		*REAR BUMPER MAT	0.00	0.00	net *50.00 F
16	1		*REVERSE SENSOR	0.00	0.00	nw *135.70 F
17	1		*TAILLAMP ASSY UPPER LH	25.00	0.00	cur *557.90 FL
18	1		*TAILLAMP ASSY LOWER LH	25.00	0.00	cur *570.00 FL
19	1		*REAR END PANEL	25.00	0.00	Ry *738.96 FL
20	1		*REAR END PANEL GARNISH	25.00	0.00	? *165.80 FL
21	1		*REAR NUMBER PLATE	0.00	0.00	bt *50.00 F
22	2		*WINDSCREEN SEALANT	0.00	0.00	net *46.00 F
23	1		*REAR BUMPER SIDE BRACKET LH	25.00	0.00	? *94.80 FL
24	1		*SEAL REAR BUMPER SIDE LH	25.00	0.00	? *148.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,587.69
- List Item Discount on L Items (\$\$)	2,326.50
Total Parts (\$\$)	7,261.19

ComfortDelGro Engineering Pte Ltd/SHC3089P/13/09/2022 14:57. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700. 1,400.00
2	SPRAYPAINT	New	750 1,000.00
3	TUFF KOTE	New	30 50.00
4	CHECK WIRING	New	30 50.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	✓ 120.00
6	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
7	TOWING FEE	New	✓ 60.00
Gross Labour Cost (S\$)			2,730.00

ComfortDelGro Engineering Pte Ltd/SHC3089P/13/09/2022 14:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphir 87495747
 WP' 14/9/22 @ 1025
 L/S Rising after repair
 3-4 days
 Tanphir @ 11/10/22


LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Date/Time: 13.09.2022 14:24

Page : 1

m: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4774861

JC N005529747

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO 7010045

IESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

DUNT CARD NO.

REGN NO:

SHC3089P

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)12.09.2022 21:15

DATE/TIME IN

YR OF MANU.

01.04.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU603079848

COMPLETION DATE/TIME:

JOB DESCRIPTION


Ident Date: 12.09.2022

PURE: 3P.12.09.22

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

To be kept by Security Guard

returned to Service Reception upon collection

Date

Name of Service Advisor

Signature/Date

Name of Service Advisor

PORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 679701

Mainline +65 6388 6280 Facsimile +65 6280 9755

Service Centres

205 Braddell Road Singapore 679701

45 Pandan Road Singapore 609286

7 Sungei Kadut Way Singapore 728791

59 Loyang Drive Singapore 509969

363 Sg Ming Drive Singapore 575711

320 Ubi Road 3 Singapore 408640

6553 1111

SPARK Assist

Recovery • Towing • Accident

Appointed Partners



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 12/9/2007 Time Received: 10:03		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☒ STK (Boon Lay)		4. Type of Towing: ☐ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up	
2. ☒ New ☐ SPARK Kakis Name of Customer : Contact No. : 97859719 Vehicle No. : SK3089P Make / Model / Colour : Pass Sg Tengah Email :		5. Nature of Service: ☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery		6. Parts Replaced/Remarks:	
7. Location: Sg Tengah Rd		8. Vehicle Tow - In Workshop:			
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:		☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi			

10. Odometer Reading :

Fuel Level :

F 1/4 1/2 3/4 E

11. Radio / CD Player

☐ OK
☐ Faulty
☐ Not tested

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☒ GAO ☐ OTHERS


Name of Driver :

Vehicle No. :

Time Dispatch :

Time of Arrival :

Time Completed :


 # : Cracked X : Dented
 / : Scatched O : Missing

Signature of Customer

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement