

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD #04-01

SUNTEC TOWER FIVE

SINGAPORE 038985

TEL: 68299199

FAX: 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C

Claim Type: Own Damage

Accident Date: 12/09/2022

Estimate No: EST2201077

Date: 12 Sep 2022

Policy No: DMC22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150
5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT CORNER PANEL - LH <i>scu</i>		1 PC	296.45	296.45
2 FRONT CORNER PANEL INNER BRACKET - LH <i>bt</i>		1 PC	49.20	49.20
3 FRONT GRILLE <i>repair</i>		1 PC	393.20	393.20
4 FRONT GRILLE SEAL <i>X</i>		1 PC	69.70	69.70
5 HEAD LAMPS	LH <i>con</i>	1 PC	1,589.40	1,589.40
6 HEAD LAMP LOWER SEAL - LH <i>scu</i>		1 PC	78.50	78.50
7 FRONT DOOR V - LH <i>bt</i>		1 PC	985.20	985.20
8 FRONT DOOR FRONT COVER GARNISH - LH <i>X</i>		1 PC	96.80	96.80
9 FRONT DOOR RUBBER - LH <i>scu</i>		1 PC	245.70	245.70
10 FRONT DOOR LOWER SEAL - LH <i>scu</i>		1 PC	96.90	96.90
11 FRONT DOOR HINGE - RH - LH <i>bt</i>		1 PC	78.10	78.10
12 FRONT DOOR LOCK - RH - LH <i>X</i>		1 PC	257.30	257.30
13 FRONT DOOR CATCH - RH - LH <i>X</i>		1 PC	96.50	96.50
14 FRONT DOOR CHECKER - LH <i>X</i>		1 PC	98.70	98.70
15 FRONT DOOR INNER TRIMBOARD - LH <i>scu</i>		1 PC	698.60	698.60
16 FRONT DOOR PILLAR OUTER - LH <i>repair</i>		1 PC	497.80	497.80
17 FRONT DOOR PILLAR RUBBER - LH <i>cut</i>		1 PC	239.20	239.20
18 FRONT SIDE MIRROR STAY - LH <i>X</i>		1 PC	479.20	479.20
19 FRONT SIDE MIRROR (BIG) - LH <i>X</i>		1 PC	267.30	267.30
20 FRONT DOOR PILLAR COVER GARNISH - LH <i>X</i>		1 PC	138.70	138.70
21 FRONT WHEEL ARCH PANEL SIDE SEAL - LH <i>scu</i>		1 PC	119.70	119.70
22 FRONT FLOOR PANEL <i>X</i>		1 PC	1,557.50	1,557.50
23 FRONT CABIN LOWER STEP GARNISH - LH <i>con</i>		1 PC	214.90	161.18
24 FRONT CABIN LOWER STEP OUTER PANEL - LH <i>con repair</i>		1 PC	247.40	185.55
25 FRONT BUMPER <i>form</i>		1 PC	423.90	423.90
26 FRONT BUMPER BRACKET <i>bt</i>		1 PC	267.10	267.10
27 FRONT BUMPER FOG LAMP COVER <i>cut</i> LH		1 PC	98.50	98.50
28 AIR-CON LIQUID PIPE <i>bt</i>		1 PC	297.20	297.20
29 AIRCON DISCHARGE PIPE <i>X</i>		1 PC	379.20	379.20
30 AIR CON CONDENSER FAN ASSY <i>con</i>		1 PC	695.70	695.70
31 AIRCON CONDENSER <i>bt</i>		1 PC	1,078.60	1,078.60
32 AIRCON CONDENSER BRACKET <i>bt</i>		1 PC	289.10	289.10
33 AIRCON RECEIVER DRIER <i>X</i>		1 PC	197.40	197.40
34 FRONT WHEEL RIM <i>X</i> - LH		1 PC	398.10	398.10
				12,901.18

Special Net

35 FRONT DOOR SIDE LETTERING/PANEL MARKER	LH	nec	1 PC	20.00	20.00
---	----	-----	------	-------	-------

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985

TEL: 68299199 FAX: 68299247,68299248
ATTN: Motor Claim Department

Your Ref No: GBK9340C
Claim Type: Own Damage
Accident Date: 12/09/2022

Estimate No: EST2201077
Date: 12 Sep 2022
Policy No: DMCG22000704
Veh Reg No: GBK9340C
Make/Model: TOYOTA DYNA 150
5MT
Chassis No: JTFAT35YX0K216252
Engine No: 1KDB068625
Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
36 FRONT DOOR INNER TRIMBOARD CLIPS - LH <i>ME</i>		1 SET	65.00	<i>40</i> 65.00
37 FRONT CABIN LOWER STEP GARNISH CLIPS - LH <i>ME</i>		1 PC	20.00	20.00
				105.00
To Repair				
38 FRONT CABIN LOWER STEP INNER PANEL - LH		1 PC	471.40	0.00
				0.00
Labour				
39 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS, JACK, STRAIGHTEN, CUT, WELD, REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.		1 JOB	1,200.00	<i>600</i> 1,200.00
40 LABOUR TO TRANSFER DAMAGED FRONT DOOR-LH ATTACHMENTS TO NEW DOOR.		1 JOB	80.00	<i>60</i> 80.00
41 LABOUR TO AIRCON JOB, CHECK, CHANGE PARTS AND REFILL GAS.		1 JOB	180.00	<i>120</i> 180.00
42 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	1,200.00	<i>600</i> 1,200.00
43 LABOUR TO REMOVE UPHOLSTERY SEATS, TRIM BOARD, INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.		1 JOB	150.00	<i>60</i> 150.00
44 LABOUR TO REMOVE, CHECK UNDER CARRIAGE AND REPLACE NEW RIM.		1 JOB	120.00	X 120.00
45 LABOUR TO CONDUCT 4XWHEEL ALIGNMENT		1 JOB	90.00	X 90.00
				3,020.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985

TEL: 68299199

FAX: 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C

Claim Type: Own Damage

Accident Date: 12/09/2022

Estimate No: EST2201077

Date: 12 Sep 2022

Policy No: DMCG22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150
5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Total	S\$ 16,026.18
Add GST @ 7%	1,121.83
Total Amount payable	S\$ 17,148.01

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND ONE HUNDRED FORTY EIGHT AND CENTS ONE ONLY

For WILLIAM'S AUTO PTE LTD



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul

Hp 90010068

5 days

P/P

14/09/22 @ 1520

EXCESS: TBA

Revert

Resurvey before paint
& old parts