

M/S : ERGO INSURANCE PTE LTD
 5 TEMASEK BOULEVARD #04-01
 SUNTEC TOWER FIVE
 SINGAPORE 038985
TEL: 68299199
ATTN: Motor Claim Department
FAX: 68299247,68299248
Estimate No: EST2201077
Date: 12 Sep 2022
Policy No: DMC22000704
Veh Reg No: GBK9340C
Make/Model: TOYOTA DYNA 150
 5MT
Chassis No: JTFAT35YX0K216252
Engine No: 1KDB068625
Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
List Price				
1 FRONT CORNER PANEL	- LH Scal	1 PC	296.45	296.45
2 FRONT CORNER PANEL INNER BRACKET	- LH Scal	1 PC	49.20	49.20
3 FRONT GRILLE	repair	1 PC	393.20	393.20
4 FRONT GRILLE SEAL	Xan	1 PC	69.70	69.70
5 HEAD LAMPS		1 PC	1,589.40	1,589.40
6 HEAD LAMP LOWER SEAL	- LH Scal	1 PC	78.50	78.50
7 FRONT DOOR	- LH Scal	1 PC	985.20	985.20
8 FRONT DOOR FRONT COVER GARNISH	- LH Scal	1 PC	96.80	96.80
9 FRONT DOOR RUBBER	- LH Scal	1 PC	245.70	245.70
10 FRONT DOOR LOWER SEAL	- LH Scal	1 PC	96.90	96.90
11 FRONT DOOR HINGE - RH	- LH Scal	1 PC	78.10	78.10
12 FRONT DOOR LOCK - RH	- LH Scal	1 PC	257.30	257.30
13 FRONT DOOR CATCH - RH	- LH Scal	1 PC	96.50	96.50
14 FRONT DOOR CHECKER	- LH Scal	1 PC	98.70	98.70
15 FRONT DOOR INNER TRIMBOARD	- LH Scal	1 PC	698.60	698.60
16 FRONT DOOR PILLAR OUTER	- LH Scal	1 PC	497.80	497.80
17 FRONT DOOR PILLAR RUBBER	- LH Scal	1 PC	239.20	239.20
18 FRONT SIDE MIRROR STAY	- LH Scal	1 PC	479.20	479.20
19 FRONT SIDE MIRROR (BIG)	- LH Scal	1 PC	267.30	267.30
20 FRONT DOOR PILLAR COVER GARNISH	- LH Scal	1 PC	138.70	138.70
21 FRONT WHEEL ARCH PANEL SIDE SEAL	- LH Scal	1 PC	119.70	119.70
22 FRONT FLOOR PANEL	- LH Scal	1 PC	1,557.50	1,557.50
23 FRONT CABIN LOWER STEP GARNISH	- LH Scal	1 PC	214.90	214.90
24 FRONT CABIN LOWER STEP OUTER PANEL	- LH Scal	1 PC	247.40	247.40
25 FRONT BUMPER	repair	1 PC	423.90	423.90
26 FRONT BUMPER BRACKET	bt	1 PC	267.10	267.10
27 FRONT BUMPER FOG LAMP COVER	bt	1 PC	98.50	98.50
28 AIR-CON LIQUID PIPE	bt	1 PC	297.20	297.20
29 AIRCON DISCHARGE PIPE	Xan	1 PC	379.20	379.20
30 AIR CON CONDENSER FAN ASSY	bt	1 PC	695.70	695.70
31 AIRCON CONDENSER	bt	1 PC	1,078.60	1,078.60
32 AIRCON CONDENSER BRACKET	bt	1 PC	289.10	289.10
33 AIRCON RECEIVER DRIER	Xan	1 PC	197.40	197.40
34 FRONT WHEEL RIM	Xan	1 PC	398.10	398.10
				12,901.18

Special Net

35 FRONT DOOR SIDE LETTERING/PANEL MARKER	LH Scal	1 PC	20.00	20.00
---	--------------------	------	-------	-------

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
 TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg
 GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S: ERGO INSURANCE PTE LTD
 5 TEMASEK BOULEVARD #04-01
 SUNTEC TOWER FIVE
 SINGAPORE 038985
 TEL: 68299199 FAX: 68299247,68299248
 ATTN: Motor Claim Department

Estimate No: EST2201077
 Date: 12 Sep 2022
 Policy No: DMC22000704
 Veh Reg No: GBK9340C
 Make/Model: TOYOTA DYNA 150
 5MT
 Chassis No: JTFAT35YX0K216252
 Engine No: 1KDB068625
 Reg. Date: 25/01/2021

Your Ref No: GBK9340C
 Claim Type: Own Damage
 Accident Date: 12/09/2022

Estimate Repair Cost to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
36 FRONT DOOR INNER TRIMBOARD CLIPS - LH <i>M/</i>		1 SET	SS 65.00	SS 65.00
37 FRONT CABIN LOWER STEP GARNISH CLIPS - LH <i>M/</i>		1 PC	20.00	20.00
				105.00
To Repair				
38 FRONT CABIN LOWER STEP INNER PANEL - LH		1 PC	471.40	0.00
				0.00
Labour				
39 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS,JACK,STRAIGHTEN,CUT,WELD,REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.		1 JOB	1,200.00	1,200.00 600
40 LABOUR TO TRANSFER DAMAGED FRONT DOOR-LH ATTACHMENTS TO NEW DOOR.		1 JOB	80.00	80.00 60
41 LABOUR TO AIRCON JOB,CHECK,CHANGE PARTS AND REFILL GAS.		1 JOB	180.00	180.00 120
42 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	1,200.00	1,200.00 600
43 LABOUR TO REMOVE UPHOLSTERY SEATS,TRIM BOARD,INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.		1 JOB	150.00	150.00 60
44 LABOUR TO REMOVE,CHECKUNDER CARRIAGE AND REPALCE NEW RIM.		1 JOB	120.00	120.00 X
45 LABOUR TO CONDUCT 4XWHEEL ALIGNMENT		1 JOB	90.00	90.00 X
				3,020.00

80.00
 1440.00
 6287.81

710 - \$6,287.81 / 5 days