

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapisp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD #04-01
SUNTEC TOWER THREE
SINGAPORE 038988

TEL: 68299199 - FAX: 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C

Claim Type: Own Damage

Accident Date: 12/09/2022

Claim No: EST2201077

Final No: CL2301073

Date: 02 Mar 2023

Policy No: DMCG22000704

Veh Reg No: **GBK9340C**

Make/Model: TOYOTA DYNA 150 5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Tax Invoice to Vehicle No :GBK9340C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1 FRONT CORNER PANEL - LH	1 PC	255.00	
2 FRONT CORNER PANEL INNER BRACKET - LH	1 PC	49.20	
3 HEAD LAMPS LH	1 PC	727.10	
4 HEAD LAMP LOWER SEAL - LH	1 PC	48.50	
5 FRONT DOOR V - LH	1 PC	985.20	
6 FRONT DOOR RUBBER - LH	1 PC	146.00	
7 FRONT DOOR LOWER SEAL - LH	1 PC	96.90	
8 FRONT DOOR HINGE - RH - LH	1 PC	78.10	
9 FRONT DOOR INNER TRIMBOARD LH	1 PC	430.00	
10 FRONT DOOR PILLAR RUBBER LH	1 PC	239.20	
11 FRONT WHEEL ARCH PANEL SIDE SEAL - LH	1 PC	119.70	
12 FRONT CABIN LOWER STEP GARNISH - LH	1 PC	161.18	
13 FRONT BUMPER	1 PC	423.90	
14 FRONT BUMPER BRACKET	1 PC	138.00	
15 FRONT BUMPER FOG LAMP COVER LH	1 PC	98.50	
16 AIR-CON LIQUID PIPE	1 PC	297.20	
17 AIR CON CONDENSER FAN ASSY	1 PC	695.70	
18 AIRCON CONDENSER	1 PC	1,078.60	
19 AIRCON CONDENSER BRACKET	1 PC	289.10	
		6,357.08	
	Less 25%	1,589.27	4,767.81
Special Net			
20 FRONT DOOR SIDE LETTERING/PANEL MARKER LH	1 PC	20.00	
21 FRONT DOOR INNER TRIMBOARD CLIPS - LH	1 SET	40.00	
22 FRONT CABIN LOWER STEP GARNISH CLIPS - LH	1 PC	20.00	
		80.00	80.00
To Repair			
23 FRONT DOOR PILLAR OUTER - LH	1 PC	497.80	
24 FRONT FLOOR PANEL	1 PC	1,557.50	
25 FRONT CABIN LOWER STEP OUTER PANEL - LH	1 PC	247.40	
26 FRONT CABIN LOWER STEP INNER PANEL - LH	1 PC	471.40	
		2,774.10	
	Less 100%	2,774.10	0.00
To Reused			
27 FRONT GRILLE	1 PC	393.20	
28 FRONT GRILLE SEAL	1 PC	69.70	
29 FRONT DOOR FRONT COVER GARNISH - LH	1 PC	96.80	

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg
GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD #04-01
SUNTEC TOWER THREE
SINGAPORE 038988

TEL: 68299199 - **FAX:** 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C

Claim Type: Own Damage

Accident Date: 12/09/2022

Claim No: EST2201077

Final No: CL2301073

Date: 02 Mar 2023

Policy No: DMC22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150 5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Tax Invoice to Vehicle No :GBK9340C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30 FRONT DOOR LOCK - RH - LH	1 PC	257.30	
31 FRONT DOOR CATCH - RH - LH	1 PC	96.50	
32 FRONT DOOR CHECKER - LH	1 PC	98.70	
33 FRONT SIDE MIRROR STAY - LH	1 PC	479.20	
34 FRONT SIDE MIRROR (BIG) - LH	1 PC	267.30	
35 FRONT DOOR PILLAR COVER GARNISH - LH	1 PC	138.70	
36 AIRCON DISCHARGE PIPE	1 PC	379.20	
37 AIRCON RECEIVER DRIER	1 PC	197.40	
38 FRONT WHEEL RIM - LH	1 PC	398.10	
		2,872.10	
	Less 100%	2,872.10	0.00
Labour			
39 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS,JACK,STRAIGHTEN,CUT,WELD,REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.	1 JOB	600.00	
40 LABOUR TO TRANSFER DAMAGED FRONT DOOR-LH ATTACHMENTS TO NEW DOOR.	1 JOB	60.00	
41 LABOUR TO AIRCON JOB,CHECK,CHANGE PARTS AND REFILL GAS.	1 JOB	120.00	
42 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS	1 JOB	600.00	
43 LABOUR TO REMOVE UPHOLSTERY SEATS,TRIM BOARD,INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.	1 JOB	60.00	
		1,440.00	1,440.00
Total			S\$ 6,287.81
Add GST @ 7%			440.15
Total Amount Payable			S\$ 6,727.96

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SEVEN HUNDRED TWENTY SEVEN AND CENTS NINETY SIX ONLY

The above vehicle was surveyed by LKK AUTO CONSULTANTS PTE LTD on 15/09/2022

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

E. & O. E.

伟联汽车私营有限公司
WILLIAM'S AUTO PTE LTD

HQ / WORKSHOP:

Blk c3 Woodlands Road 391-B Yew Tee Industrial Estate Singapore 677965
Tel: 67636811 (5 Lines) Fax: 67632166

Co. Reg. No: A03151/1978Z
GST Reg. No: M2-0032987-2

Our ref : EST2201077
Date of Accident : 12/09/2022

VEHICLE DISCHARGE VOUCHER

I hereby certify that the damage to my/vehicle TOYOTA DYNA 150 5MT of registration no: GBK9340C which was involved in an accident has been repaired to my/our satisfaction by WILLIAM'S AUTO PTE LTD and I/We agree that the payment of their account by ERGO INSURANCE PTE LTD shall be in full settlement of the repairs.

Date : 24/09/2022

Signature

:



Policy No

: DMCG22000704

William Auto

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Wednesday, 22 February 2023 9:01 am
To: William Auto
Subject: Re: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Hi William,

Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Monday, 13 February 2023 10:26 am
To: William Auto <waplsp21@singnet.com.sg>
Subject: Re: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Hi Mr William,

As spoken, the finalised amount is P/P \$ 6,287.81/ 5 days of repair

Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: William Auto <waplsp21@singnet.com.sg>
Sent: Friday, 10 February 2023 11:00 am
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Dear Rasul

Please check the missing Item 35 on estimate marked S. Nett \$20.00,

The correct amounts should be \$6,287.81.

Please revert to me ASAP

Thank you