

ASS. REC. BY:

REF:

CS/E6122009008/RVY3

7404

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBK 9340Cat Workshop m/s WILLIAM AUTO PLof 3, WOODLANDS RD 391-B Y&R P&EInsured: E61

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 75K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REP. / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

GBK 9340C

Yr Regn:

2021 JANType: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA DYNA 150 SMT c.c. 2982

Colour

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

60561

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ITFAT 359XOK 216252

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

155R12C☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5/5

mm

L/Bal.

7

mm

L/Bal.

5/5

mm

D.O.A.

12/09/22

D.O.I.

14/09/22

Survey held at

WILLIAM AUTO

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 47K

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.A. (%)

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985

TEL: 68299199 FAX: 68299247,68299248
ATTN: Motor Claim Department

Your Ref No: GBK9340C
Claim Type: Own Damage
Accident Date: 12/09/2022

Estimate No: EST2201077

Date: 12 Sep 2022

Policy No: DMCG22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150
5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT CORNER PANEL - LH <i>scd</i>		1 PC	296.45	296.45
2 FRONT CORNER PANEL INNER BRACKET - LH <i>bt</i>		1 PC	49.20	49.20
3 FRONT GRILLE <i>repair</i>		1 PC	393.20	393.20
4 FRONT GRILLE SEAL <i>X</i>		1 PC	69.70	69.70
5 HEAD LAMPS	LH <i>com</i>	1 PC	1,589.40	1,589.40
6 HEAD LAMP LOWER SEAL - LH <i>scd</i>		1 PC	78.50	78.50
7 FRONT DOOR V - LH <i>bt</i>		1 PC	985.20	985.20
8 FRONT DOOR FRONT COVER GARNISH - LH <i>X</i>		1 PC	96.80	96.80
9 FRONT DOOR RUBBER - LH <i>ne</i>		1 PC	245.70	245.70
10 FRONT DOOR LOWER SEAL - LH <i>ne</i>		1 PC	96.90	96.90
11 FRONT DOOR HINGE - RH - LH <i>bt</i>		1 PC	78.10	78.10
12 FRONT DOOR LOCK - RH - LH <i>X</i>		1 PC	257.30	257.30
13 FRONT DOOR CATCH - RH - LH <i>X</i>		1 PC	96.50	96.50
14 FRONT DOOR CHECKER - LH <i>X</i>		1 PC	98.70	98.70
15 FRONT DOOR INNER TRIMBOARD - LH <i>de</i>		1 PC	698.60	698.60
16 FRONT DOOR PILLAR OUTER - LH <i>repair</i>		1 PC	497.80	497.80
17 FRONT DOOR PILLAR RUBBER - LH <i>cut</i>		1 PC	239.20	239.20
18 FRONT SIDE MIRROR STAY - LH <i>X</i>		1 PC	479.20	479.20
19 FRONT SIDE MIRROR (BIG) - LH <i>X</i>		1 PC	267.30	267.30
20 FRONT DOOR PILLAR COVER GARNISH - LH <i>X</i>		1 PC	138.70	138.70
21 FRONT WHEEL ARCH PANEL SIDE SEAL - LH <i>nee</i>		1 PC	119.70	119.70
22 FRONT FLOOR PANEL <i>X</i>		1 PC	1,557.50	1,557.50
23 FRONT CABIN LOWER STEP GARNISH - LH <i>com</i>		1 PC	214.90	161.18
24 FRONT CABIN LOWER STEP OUTER PANEL - LH <i>com repair</i>		1 PC	247.40	185.55
25 FRONT BUMPER <i>torn</i>		1 PC	423.90	423.90
26 FRONT BUMPER BRACKET <i>bt</i>		1 PC	267.10	267.10
27 FRONT BUMPER FOG LAMP COVER <i>cut</i>	LH	1 PC	98.50	98.50
28 AIR-CON LIQUID PIPE <i>bt</i>		1 PC	297.20	297.20
29 AIRCON DISCHARGE PIPE <i>X</i>		1 PC	379.20	379.20
30 AIR CON CONDENSER FAN ASSY <i>com</i>		1 PC	695.70	695.70
31 AIRCON CONDENSER <i>bt</i>		1 PC	1,078.60	1,078.60
32 AIRCON CONDENSER BRACKET <i>bt</i>		1 PC	289.10	289.10
33 AIRCON RECEIVER DRIER <i>X</i>		1 PC	197.40	197.40
34 FRONT WHEEL RIM <i>X</i>	LH	1 PC	398.10	398.10
				12,901.18

Special Net

35 FRONT DOOR SIDE LETTERING/PANEL MARKER LH	1 PC	20.00	20.00
--	------	-------	-------

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapisp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD #04-01

SUNTEC TOWER FIVE

SINGAPORE 038985

TEL: 68299199

FAX: 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C

Claim Type: Own Damage

Accident Date: 12/09/2022

Estimate No: EST2201077

Date: 12 Sep 2022

Policy No: DMCG22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150
5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
36 FRONT DOOR INNER TRIMBOARD CLIPS - LH <i>me /</i>		1 SET	65.00	<i>40</i> 65.00
37 FRONT CABIN LOWER STEP GARNISH CLIPS - LH <i>me /</i>		1 PC	20.00	20.00
				105.00
To Repair				
38 FRONT CABIN LOWER STEP INNER PANEL - LH		1 PC	471.40	0.00
				0.00
Labour				
39 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS, JACK, STRAIGHTEN, CUT, WELD, REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.		1 JOB	1,200.00	<i>600</i> 1,200.00
40 LABOUR TO TRANSFER DAMAGED FRONT DOOR-LH ATTACHMENTS TO NEW DOOR.		1 JOB	80.00	<i>60</i> 80.00
41 LABOUR TO AIRCON JOB, CHECK, CHANGE PARTS AND REFILL GAS.		1 JOB	180.00	<i>120</i> 180.00
42 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	1,200.00	<i>600</i> 1,200.00
43 LABOUR TO REMOVE UPHOLSTERY SEATS, TRIM BOARD, INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.		1 JOB	150.00	<i>60</i> 150.00
44 LABOUR TO REMOVE, CHECK UNDER CARRIAGE AND REPLACE NEW RIM.		1 JOB	120.00	X 120.00
45 LABOUR TO CONDUCT 4XWHEEL ALIGNMENT		1 JOB	90.00	X 90.00
				3,020.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985

TEL: 68299199

FAX: 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C

Claim Type: Own Damage

Accident Date: 12/09/2022

Estimate No: EST2201077

Date: 12 Sep 2022

Policy No: DMCG22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150
5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Estimate Repair Cost to Vehicle No : GBK9340C

Total S\$ 16,026.18

Add GST @ 7% 1,121.83

Total Amount payable S\$ 17,148.01

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND ONE HUNDRED FORTY EIGHT AND CENTS ONE ONLY

For WILLIAM'S AUTO PTE LTD



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ramul

Hp 90010068

5 days

P/P

14/09/22 @ 1520

EXCESS: TBA

Revert

Resurvey before paint
& old parts

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/09/2022 10:25 (SGT)
Reported by	Driver
Date of Accident	12/09/2022 10:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	EAST COAST RD TOWARDS ECP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK9340C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SRI MURUGAN TRADING PTE LTD
Company Reg No	200414740H
Email Address	kumar_accounts@srimumugantrading.com
Mobile Phone No	(Phone) +65-67343045
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMCG22000704

DRIVER

Name of Driver	KAMARAJ VENKATESAN
Passport No/FIN	G6598781W
Date Of Birth	23/06/1988
Occupation	Outdoor

Date Of Driving Pass	13/05/2013
Driving experience	9 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-83513645
Alt. Phone Number	-
Email Address	kumar_accounts@srimumugantrading.com
Address	-
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER SKETCH ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS777L
Vehicle Manufacturer	Honda
Vehicle Model	Fit
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAN CHIANG LEONG
NRIC No	S1640719D

Contact Number	(Phone) +65-91451678
Address	132 LOR K TELOK KURAU #01-02
Address complement	-
Postcode	425790
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

1 VEHICLE NO: G6K 9340C
 2 INSURER CO: ARGO
 3 ACCIDENT DATE & TIME: 12/9/22 10:20 AM

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)
 I understand, acknowledge, agree and consent that :
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 (ii) investigating the accident and/or my claims;
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

SRI MURUGAN TRADING PTE LTD
 5, SECOND CHIN BEE ROAD
 SINGAPORE - 618772

W. Vaidyanathan


[Signature] 12/9/22

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time 12/9/22

Witnessed by Reporting Centre Personnel *[Signature]* (WL)

Sketch Plan



Sketch Plan



A. GBK9340C
B. SKS777L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to accident report - annex A attached

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

SRI MURUGAN TRADING PTE LTD
5, SECOND CHIN BEE ROAD
SINGAPORE 648772

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12/9/22

Reporting Centre Personnel's Signature

Name: Etudn (W)

NRIC/FIN No.:

☒ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop

MY VEHICLE NUMBER(A) : GBK9340C

NAME : KAMARAJ VENKATESAN

IC : G6598781W

MDL : TOYOTA DYNA

HP : 83513645

ACCIDENT LOCATION : EAST COAST ROAD TOWARDS ECP

DATE: 12/09/2022

TIME: 10:20 AM

ANNEX A

VEHICLE (B) : SKS777L

NAME : TAN CHIANG LEONG

IC: S1640719D

ADD: 132 LORONG K TELOK KURAU #01-02 S(425790)

MDL : HONDA FIT

I WAS TRAVELLING ALONG EAST COAST ROAD GOING TOWARDS ECP ON A 2 LANE ROAD, I WAS ON THE RIGHT LANE. THERE WAS A VEHICLE INFRONT OF ME THAT ALL OF A SUDDEN STOPPED INBETWEEN THE FIRST AND SECOND LANE ON THE CENTRE WHITE LINE, UPON SEEING THIS, I TRIED TO MAKE AN EMERGENCY BRAKE AND SWERVED MY STEERING TO THE RIGHT TO STOP MY VEHICLE AND TRIED TO AVOID THE ACCIDENT, DUE TO INSUFFICIENT SPACE ON MY RIGHT (ROAD DIVIDER) FOR ME THUS THE FRONT LEFT PORTION OF MY VEHICLE HIT ONTO THE REAR RIGHT PORTION OF THE SAID VEHICLE. THE SAID DRIVER TOLD ME THAT HE INTENDED TO PARK HIS VEHICLE INTO THE PARKING LOT ON THE LEFT SIDE.

NO INJURY INVOLVED.



SRI MURUGAN TRADING PTE LTD
5, SECOND CHIN BEE ROAD
SINGAPORE - 618772

KAMARAJ VENKATESAN

G6598781W

12/09/2022

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	740H
Vehicle No.:	GBK9340C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	1KDB068625
Chassis No.:	JTFAT35YX0K216252
Maximum Power Output:	-
Open Market Value:	\$29,446.00
Original Registration Date:	25 Jan 2021
First Registration Date:	25 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$1,473.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	24 Jan 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,588.00
COE Rebate Amount:	\$27,235.00
Total Rebate Amount:	\$27,235.00

The information contained herein is correct as at 15 Sep 2022

OK

Toyota Dyna 150 3.0M

Overview

Financial

Accessories

Similar

Research


Photos

Map



Lek Auto Pte. Ltd.

Price **\$82,800**

Depreciation  **\$9,080 /yr**
View models with similar depre


Reg Date **28-Oct-2021**
(9yrs 1mth 12days COE left)

Mileage **N.A.**


Manufactured  **2021**

Road Tax  **N.A.**

Transmission **Manual**

Dereg Value  **\$38,844 as of today (change)**

Fuel Type **Diesel**

COE  **\$42,589**

OMV  **\$32,654**

Engine Cap **2,982 cc**

ARF  **\$1,633**

Curb Weight  **1,800 kg**

No. of Owners  **1**