

ASS. REC. BY:

REF:

EQ/ 220090111K9

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMT 8274

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda 157

C.C

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

49357

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK3

3416032

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

13/9/22

Rear

R/Bal.

9

mm

L/Bal.

9

mm

D.O.I.

14/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

F. & S.

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

Not Authorized
U/Sup &
Recovery After Pain
5 days

DAVISCPOOL

c/o 46 Lenton Plain
Singapore 786548

Date : 14/09/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : HONDA FIT / SMT 827 Y		
1 pc	rear bumper	By 646.00
2 pcs	rear bumper side retainer @ 76.30	Dis 152.60
2 pcs	rear bumper side cover @ 117.40	Sm 234.80 X
2 pcs	rear bumper inner pad side @ 165.00	330.00 ?
1 pc	rear bumper inner pad centre	187.40 ?
1 pc	rear end outer panel	546.20 ?
1 pc	rear end inner panel	R 461.70 X
1 pc	rear end panel garnish	316.20 ?
1 pc	rear spare tyre panel	R 865.70 X
1 pc	rear spare tyre panel top board	R 342.10 X
2 pcs	rear fender inner trim @ 314.70	Sm 629.40 X
1 pc	rear boot lid	R 974.20
1 pc	rear boot outer garnish	463.10 ?
1 pc	rear boot lock	M 123.50
1 pc	rear boot lock catch	R 67.00 X
1 pc	rear boot lock sensor	357.80 ?
1 pc	rear boot inner trim	365.00 ?
1 pc	rear boot emblem ' FIT '	R 74.20
1 pc	rear boot emblem ' logo '	68.40 ?
2 pcs	rear boot lamp @ 663.70	dis 1,327.40 Lt
2 pcs	rear tail lamp @ 577.40	Gr 1,154.80
1 set	rear windscreen glass moulding	R 157.00
1 pc	rear windscreen wiper motor	Sm 568.70 X
1 pc	rear windscreen glass inner seal	R 60.00 3000
1 pc	exhaust silencer	R 876.40 X
1 pc	tool kit foam box	378.60 ?
sub-total		11,728.20
less 20%		2,345.64
sub-total		9,382.56

	balance bought forward.			9,382.56	
1 SET	reverse sensor	s.nett	phat	280.00	200sn
1 pc	windscreen glass sealant	s.nett	her	60.00	40sn
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.			1,300.00	600
	To check wiring system.			50.00	20l
	To apply rust proofing on affected areas.			180.00	7
	To water waterproof sealant on affected areas.		~	180.00	X
	To apply putty and spray painting on affected areas.			900.00	600
	To install reverse sensors.			100.00	60l
	To remove rear windscreen glass to enable repair.			140.00	120l
	To remove carpet, trimming and seats to enable repair.			120.00	60l
	To transfer tail doors accessories.			40.00	✓
	Total			12,732.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: