

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22009013/Rny3	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	13/09/2022	
				Code:	LPC2	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBG 2863C	Veh. Inspected		SKA 9372G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026285	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		13/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model		C.C		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes		Modification			
	General					
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Description of Damages				
5.	General Information					
	Accident Date	12/09/2022	Inspection Date	е	14/09/2022	
	Survey held at	HIAP LEK AUTOMOBILE TRADING				
		160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					