

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No.	: SLH 4056 D	Reference No.	: AMM2209-06
Chassis No.	: GP71043302	Make/Model	: HONDA / SHUTTLE 1.5 HYBRID AT ABS
Engine No.	: LEB4263118	Date	: 01.07.2023
Date of Accident	: 03.08.22		

Replacement of Damaged Parts

<u>S/No.</u>	<u>QTY</u>	<u>Description</u>	<u>Condition / Remarks</u>	<u>Repairer's</u> <u>Estimates</u>	<u>My</u> <u>Recommendation</u>
1	1	Front Bumper		\$ 820.00	\$ 738.00
2	1	Front Fender RH		\$ 282.00	\$ 253.80
3	1	Headlamp RH		\$ 738.00	\$ 664.20
4	1	Front Wheel Cap RH		\$ 45.00	\$ 40.50
5	1	Front Bumper Beam RH		\$ 35.00	\$ 31.50
6	1	Front Bumper Spacer RH		\$ 22.00	\$ 19.80
7	1	Front Wheel Cowling Inner RH		\$ 108.00	\$ 97.20
8					\$ -
9					\$ -
10					\$ -
				\$ 2,050.00	\$ 1,640.00

Total (Parts): \$ 2,050.00 -20% \$ 1,640.00

Labour Charges

26	To fix & dismantle and remove damaged Front Portions; affected damaged portion.	\$ 600.00
27	To apply anti rust coat and affected areas	
28	To check wiring	\$ 180.00
29	Welding and cutting of affected panels, including chassis alignment.	
30	Spray painting for Front Portions affected parts	\$ 800.00
31	Refocusing of the front headlamp	
32	Diagnose ECU system and reset error code.	
33	3D Wheel Alignment	\$ 120.00
34	To Apply Waterproofing sealer on Front Support Panels	

Total Labour: \$ 1,700.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 3,340.00

Less 20% **\$ 2,672.00**