

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0783/2022/EQ
DATE : 8-Sep-22
WIP : 40741

Xiao Chun.

\$13149.44.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ANKIT KHETAN
ADDRESS : 21 KIM YAM ROAD
#08-04
SINGAPORE 239332
TELEPHONE : HP +65 92301054
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220056111
VEHICLE NO : SNF 3735 X
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 24/5/2022
ENGINE NO : DEM 031711
CHASSIS NO : WAUZZZF54MA039952
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Sep-22
PLACE OF ACCIDENT : 12 MARINA VIEW, SINGAPORE 018961

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 3735 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	259 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000 ✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,500.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,972.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3735 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>torn</i>	1	\$ 2,493.00	✓ 1994.40
2	FRONT BUMPER SECURING STRIP <i>Not new</i>	2	\$ 79.00	✗
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not torn</i>	1	\$ 293.00	234.00 ✓
5	FRONT BUMPER SPOILER <i>new</i>	1	\$ 599.00	+
6	RADIATOR AIR GUIDE - RH <i>new</i>	1	\$ 72.00	+
7	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 293.00	+
8	RADIATOR AIR GUIDE GRILLE - RH <i>let</i>	1	\$ 151.00	✓ 120.40
9	FRONT BUMPER OUTER GRILLE HOLE COVER - RH <i>new</i>	1	\$ 54.00	+
10	RADIATOR GRILLE TRIM - CENTER <i>new</i>	1	\$ 127.00	+
11	RADIATOR GRILLE <i>2</i>	1	\$ 1,881.00	+
12	RADIATOR GRILLE CAP COVER <i>new</i>	1	\$ 141.00	+
13	RADIATOR GRILLE BRACKET <i>new</i>	1	\$ 19.00	+
14	FRONT CAMERA <i>Not new</i>	1	\$ 1,264.00	+
15	FRONT BUMPER GUIDE SECTION - RH <i>Not new</i>	1	\$ 41.00	✗
16	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 163.00	+
17	FRONT BUMPER REINFORCEMENT BEAM <i>Not new</i>	1	\$ 899.00	+
18	FRONT BUMPER TOP COVER <i>Not new</i>	1	\$ 143.00	+
19	CAUTION SIGN STICKER <i>Not new</i>	1	\$ 16.00	+
20	AIR CONDITIONER STICKER <i>Not new</i>	1	\$ 9.00	+
SUB TOTAL SPARE PARTS		:	\$ 8,956.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3735 X

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
21	LOCK CARRIER BRACKET <i>Neu</i>	1	\$	154.00	+	
22	FRONT BUMPER SUPPORT - LH <i>Neu</i>	2	\$	64.00	+	
23	FRONT PARKING AID SENSOR - INNER / OUTER <i>Neu</i>	2	\$	532.00	+	
24	FRONT PARKING AID SEAL RING <i>Neu</i>	4	\$	10.00	+	
25	FRONT BUMPER WIRING SET	1	\$	449.00	+	
26	HORN LOW TONE - RH <i>Neu</i>	1	\$	139.00	+	
27	HORN BRACKET - RH <i>Neu</i>	1	\$	33.00	+	
28	FRONT FENDER - RH <i>Dented</i>	1	\$	1,189.00	✓	951.20
29	FRONT FENDER ATTACHMENT PARTS <i>Neu</i>	1	\$	55.00	+	
30	FRONT FENDER CLOSING ELEMENT - RH <i>Neu</i>	1	\$	83.00	+	
31	FRONT FENDER BRACKET - RH <i>Neu</i>	1	\$	41.00	+	
32	FRONT FENDER RIVET <i>Neu</i>	6	\$	23.00	✓	18.24
33	FRONT FENDER BRACE - RH <i>Neu</i>	1	\$	132.00	+	
34	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>Neu</i>	1	\$	55.00	+	
35	FRONT FENDER TRIM - RH <i>Dented</i>	1	\$	171.00	?	136.40 ✓
36	FRONT WHEEL HOUSING LINER - RH <i>Neu</i>	1	\$	299.00	+	
37	FRONT WHEEL SPOILER - RH <i>Neu torn</i>	1	\$	82.00	+	65.12 ✓
38	FRONT STONE CHIP GUARD - RH <i>Neu</i>	1	\$	57.00	+	
39	FRONT SPOILER END PLATE - RH <i>Neu</i>	1	\$	40.00	+	
40	HEADLIGHT - RH <i>Neu</i>	1	\$	8,172.00	✓	6537.60
SUB TOTAL SPARE PARTS			:	\$ 11,780.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3735 X

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	LIFT CYLINDER - RH	1	\$	217.00	+
42	LIFT CYLINDER CORRUGATED PIPE	1	\$	107.00	+
43	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	21.00	+
44	RADIATOR AIR DUCT - RH	1	\$	36.00	+
45	RADIATOR AIR DUCT - RH	1	\$	19.00	+
46	RADIATOR AIR GUIDE - UPPER	1	\$	19.00	+
47	RADIATOR AIR GUIDE - LOWER	1	\$	25.00	+
48	FRONT NO PLATE	S/N	\$	60.00	+
49	SUNDRIES		\$	400.00	?X
TOTAL SPARE PARTS		:	\$	21,640.00	
TOTAL LABOUR CHARGES		:	\$	5,972.00	
GRAND TOTAL		:	\$	27,612.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Xiao Chun.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0783/2022/EQ

28-Oct-22

CHANG



1 of 1

SNF 3735 X

AUDI A5 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	HEADLIGHT COVER - RH UPPER	\$ 49.00	38.64
2	FRONT FENDER TOP COVER - RH	\$ 40.00	31.44
GRAND TOTAL		\$ 89.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling.
H.S.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
 SURVEYED DATE : *18/09/22*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 04 Days* *[Signature]*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: