

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009026/UYA3Q2**Date:** 09/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900150230
Claimant Vehicle No :	SLB8717K	Insured Vehicle No :	SJS5295P
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	4825180461SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB8717K		
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT AWD S/R FACELIFT (A)	Engine No:	4B12QQ1822
Reg. Date:	08/04/2016 (Man. Year: 2015)	Chassis No:	JMYXTGF3WGWZ002192
Colour:	Blue	Odometer:	161552 km
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,252.30	3,521.70	2,730.60	43.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	870.00	960.00	52.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,082.30	4,391.70	3,690.60	45.66
Approved Total (Overridden) (\$\$)		3,500.00		
(\$\$)	8,082.30	3,500.00	4,582.30	56.70
+ GST 7.00/7.00% (\$\$)	565.76	245.00	320.76	56.70
Nett Amount (\$\$)	8,648.06	3,745.00	4,903.06	56.70
+ Car Rental (3.0 x S\$120.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,107.00		

INSPECTION

Date of Assignment:	14/09/2022	
Date Inspected:	14/09/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Warped / Torn	863.00 FL	*863.00 FL
2	1		*FRONT BUMPER CENTRE GARNISH (BLACK)	Not Necessary	517.00 FL	*- FL
3	1		*FRONT BUMPER CENTRE CHROME GARNISH	Not Necessary	321.00 FL	*- FL
4	1		*FRONT BUMPER N/S CHROME MOULDING LOWE	Scratched	112.00 FL	*112.00 FL
5	1		*FRONT BUMPER N/S CHROME MOULDING TOP	Scratched	220.00 FL	*220.00 FL
6	1		*FRONT BUMPER FOG LAMP N/S	Cracked	348.00 FL	*348.00 FL
7	1		*FRONT BUMPER FOG LAMP COVER N/S	Scratched	68.00 FL	*68.00 FL
8	1		*FRONT BUMPER BEAM	Not Necessary	305.00 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	45.00 FL	*45.00 FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
11	1		*HEADLAMP N/S	Holder Cracked	2,548.00 FL	*1,948.00 FL
12	1		*HEADLAMP NOZZLE N/S	Cracked	299.00 FL	*221.00 FL
13	1		*HEADLAMP NOZZLE COVER N/S	Cut	53.00 FL	*38.00 FL
14	1		*FRONT GRILLE ASSY	Not Necessary	550.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Repair	648.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					6,947.00	3,913.00
- List Item Discount on L Items 10.00/10.00% (S\$)					694.70	391.30
Total Parts (S\$)					6,252.30	3,521.70
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX FRONT PDC SENSOR	New	80.00	0.00
3	TO RESET & DIAGNOSTIC SYSTEM	New	120.00	0.00
4	TO SPRAY RUST PROOFING	New	60.00	0.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	450.00
7	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			1,830.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >